

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
MURILLO		MIGUEL		M640540601260			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	02/13/2023	229620	ROWLAND TRANSPORTATION INC	MURILLO, MIGUEL	M640540601260	FL	04/06/1960	SC	C326001754	N	2	0			

Report executed at: 6/9/2025 9:51:22 AM

MCMIS snapshot date: 04/25/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	11/25/2024	3655676	BONANZA CARRIERS LLC	MURILLO, MIGUEL	M640540601260	FL	04/06/1960	OH	3297000121	N	2	2
Vehicle Violation:		393.95A4-EEUS	EMERGENCY EQUIPMENT - FIRE EXTINGUISHERS - UNSECURED			NON-OOS						
Vehicle Violation:		393.55D2-B	AIR BRAKE - ABS MALFUNCTION LAMP DEFECTIVE ON TRUCK-TRACTOR MANUFACTURED ON OR AFTER MARCH 1, 2001 FOR TOWED VEHICLE.			NON-OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.95A4-EEUS		EMERGENCY EQUIPMENT - FIRE EXTINGUISHERS - UNSECURED							1		0	
393.55D2-B		AIR BRAKE - ABS MALFUNCTION LAMP DEFECTIVE ON TRUCK-TRACTOR MANUFACTURED ON OR AFTER MARCH 1, 2001 FOR TOWED VEHICLE.							1		0	

The summary counts and rates only include violations that were attributable to MURILLO, MIGUEL.

Report executed at: 6/9/2025 9:51:22 AM

MCMIS snapshot date: 04/25/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.