PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																			
Last Name First Name					License #						State								
ALVAREZALAMO ROILAN				A416720893620						FL									
	Crash Activity																		
Crash	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																		
	# of Crashes: 0 # of Crashes with Fatalities: 0 # of Crashes with Injuries: 0 # of Towaways:											/aways: 0							
# Not preventable: 0					# of Fataliti			0					# of Ir	njuries:	0	# of Hazmat Releases:			eleases: 0
Crash	Details (C	ashes listed r	epresent a driv	er's involven	er's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)														
				er Name Driver Name									t St Report Number Location			# Fatalities # of Injur		# of Injuries	
	Julo	50. "	Garrior	Carrot Name			_	State Biver Bo				pr or	Troport Humber 200aio		" " "		" or injurior		
	,			lr	nspect	ion Activity (3 year	r histo	ory fr	rom MCN	IIS sn	apsho	t date	:)						
Inspe	ction Sumn	nary																	
		Driver	Summary			,	Vehicle	Sumi	mary						Н	azmat Sumi	nary		
Driver Inspections: 4 Vehicle Inspections: 3 Hazmat Inspections										1									
Driver Out-of-service Inspections:					0 v	Vehicle Out-of-service Inspections:					1 Ha	1 Hazmat Out-of-service Inspections: 0							
Driver Out-of-service Rate:				0% V	Vehicle Out-of-service Rate: 33%					33% Ha	Hazmat Out-of-service Rate: 0%								
Inspe	Inspection Details																		
Carrie	Carrier Info Driver Info Inspection Info																		
Date DOT# Carrier Name Driver Name								Driver Lic		State	Driver		Rpt St		Number	Hazmat	Insp I	_evel # of	
25.1.																Insp		Viol	
1	02/14/202	4 2960200	UZB FREIO	SHT INC	ALVARE	Z ALAMO, ROILAN		A	4167208936	520	FL	10/02/	/1989	NM	2434	D19B24	Y	2	1
	Vehic	e Violation:	396.5(a)			SIBLE OR MEASURABLE DUTER WHEEL	LUBRIC	CANT	SHOWING		C	oos	<u> </u>						

Report executed at: 6/23/2025 5:57:23 PM

MCMIS snapshot date: 06/06/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	05/14/2024	1437731	STAR TRANSPORTATION PA INC	ALVAREZ ALAMO, ROILAN	A416720893620	FL	10/02/1989	SD	5820000375	N	3	0
3	07/03/2024	1437731	STAR TRANSPORTATION	ALVAREZ ALAMO, ROILAN	A416720893620	FL	10/02/1989	NV	7109028014	N	2	0
3	07/03/2024	1407731	STAR TRANSPORTATION	ALVANLE ALAINO, NOILAN	A410720093020	1.5	10/02/1909	IVV	7103020014	14		
4	07/29/2024	3122310	TEN FOUR GROUP INC	ALAMO, ROILAN	A416720893620	FL	10/02/1989	NC	0006670832	N	1	0
					•						•	

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
396.5(a)	HUBS - NO VISIBLE OR MEASURABLE LUBRICANT SHOWING IN THE HUB - OUTER WHEEL	1	1

The summary counts and rates only include violations that were attributable to ALVAREZALAMO, ROILAN.

Report executed at: 6/23/2025 5:57:23 PM

MCMIS snapshot date: 06/06/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.