PSP Detailed Report

Federal Motor Carrier Safety Administration

						Driv	er Inforr	nation										
Last	Name			First Nam	me		License	License #				State						
GAR	CIA			ANGEL 3			3741827	37418272					TX					
DELA	AROSAGARCI	Ą		ANGEL			3741827	37418272					TX					
DELA	AROSA			ANGEL			3741827	37418272					TX					
	Crash Activity																	
Cras	sh Summary	(Crashes liste	d represent	driver's	s involvemen	t in FMCSA-reportable	crashes,	withou	ıt any	deter	mination as	to resp	onsibili	ty.)				
# N-4			0		# of Crashes with Fatal					# of Crash	ijuries:	0	# of Toway		vaways:	0		
# Not preventable:				0		ilities: 0			# of Injuries: 0				# of Hazmat Releases: 0			0		
Cras	sh Details (C	rashes listed r	epresent a d	river's in	nvolvement ir	n FMCSA-reportable cr	ashes, w	thout a	ny de	termi	nation as to	respon	sibility.)				
Date DOT # Carrier			er Name	Name Driver Name		Driv	Driver Lic Sta		State	tate Driver DOB Rpt St		t Report Number		Location	# Fatalities	# Injuri	ies	
Inspection Activity (3 year history from MCMIS snapshot date)																		
Insp	ection Sum	mary																
		Driver	Summary			Vehicle Summary				Hazmat Summary								
Driver Inspections:					5	Vehicle Inspections:					4 H	Hazmat Inspections					0	
Driver Out-of-service Inspections:					2	Vehicle Out-of-service Inspections:					1 Hazmat Out-of-se			-of-service Inspections:				0
Driver Out-of-service Rate:					40%	Vehicle Out-of-service Ra	ite:	: 25%			25% H	Hazmat Out-of-service Rate:					0%	

Report executed at: 4/22/2022 1:53:42 PM

MCMIS snapshot date: 03/25/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspec	tion Details													
Carrier	· Info			Driver Info	Driver Info					Inspection Info				
	Date DOT # Carrier Name			Driver Name	Driver Lic	State	tate Driver DOB Rpt St		Report Number	Hazmat Insp	Insp Level	# of Viol		
1	09/15/2019	1673199	LUNA TRUCKING	DE LA ROSA GARCIA, ANGEL	37418272	TX	07/15/1997	СО	PF08402155	N	1	15		
	Vehicle Violation: 393.9(a) Inoper			operative turn signal	erative turn signal NON-OOS									
	Vehicle V	iolation:	393.9(a)	operative turn signal		NON-0	oos							
	Vehicle V	iolation:	393.9(a)	operable Required Lamp		NON-0	oos							
	Vehicle V	iolation:	393.45(d) E	rake Connections with Leaks Under Vehicle		NON-0	oos							
	Vehicle V	iolation:	393.48(a) lı	operative/defective brakes		NON-C	oos							
	Vehicle V	iolation:	393.83(g) E	xhaust leak under driver and/or sleeper compar	tment	NON-C	oos							
	Vehicle V	iolation:	393.81 H	rn inoperative NON-OOS										
	Vehicle V	iolation:	396.5(b)	oil and/or grease leak NON-OOS										
	Vehicle Violation: 393.95(a) No/disc			oldischarged/unsecured fire extinguisher NON-OOS										
	Vehicle Violation: 393.95(b) No spa			No spare fuses as required NON-OOS										
	Vehicle Violation: 396.17(c) Opera		perating a CMV without proof of a periodic inspection NON-OOS			oos								
	Vehicle Violation: 396.17(c) Opera		Operating a CMV without proof of a periodic inspection NON-OOS											
				o or Defective ABS Malfunction Indicator Lamp lanufactured after 03/01/1998	or Defective ABS Malfunction Indicator Lamp for trailer NON-OOS nufactured after 03/01/1998									
	Driver Violation: 395.22(g) Portab		able ELD not mounted in a fixed position and visible to driver N			oos								
	Driver Violation: 395.8(a)(1) EL		395.8(a)(1)	LD - No record of duty status (ELD Required)			oos							
2	09/24/2019	1673199	LUIS LUNA	DE LA ROSA GARCIA, ANGEL	37418272	TX	07/15/1997	NM	3546403428	N	2	0		
3	02/03/2020	3004031	NEW DISCOVERY LINE CANADA LTD	S DE LA ROSA GARCIA, ANGEL	37418272	TX	07/15/1997	СО	2B24000091	N	3	2		
	Vehicle Violation: 393.9(a) Inope			perable tail lamp NON-OOS										
	Driver Vi	olation:	395.3(a)(3)-PROP	riving beyond 11 hour driving limit. (Property Ca	arrying Vehicle)	(oos			_				
4	07/04/2020	3343144	KCN LOGISTICS LLC	DE LA ROSA GARCIA, ANGEL	37418272	TX	07/15/1997	TX	5S2I0XPWKU	N	2	3		
	Vehicle V	iolation:	393.9(a)	erable Required Lamp NON-OOS										
	Vehicle V	iolation:	393.205(c) V	el fasteners loose and/or missing OOS										
	Vehicle Violation: 393.207(b) Adjust			ustable axle locking pins missing or not engaged NON-OOS										

Report executed at: 4/22/2022 1:53:42 PM

MCMIS snapshot date: 03/25/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

5	02/23/2021	1814491	ISRRAEL DE LA ROSA PEREZ	DE LA ROSA GARCIA, ANGEL	37418272	TX	07/15/1997	MS	3010010202	N	1	0

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.9(a)	Inoperative turn signal	5	0
393.45(d)	Brake Connections with Leaks Under Vehicle	1	0
393.48(a)	Inoperative/defective brakes	1	0
393.83(g)	Exhaust leak under driver and/or sleeper compartment	1	0
393.81	Horn inoperative	1	0
396.5(b)	Oil and/or grease leak	1	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.95(b)	No spare fuses as required	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	2	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0
395.8(a)(1)	ELD - No record of duty status (ELD Required)	1	1
395.3(a)(3)-PROP	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)	1	1
393.205(c)	Wheel fasteners loose and/or missing	1	1
393.207(b)	Adjustable axle locking pins missing or not engaged	1	0

The summary counts and rates only include violations that were attributable to GARCIA, ANGEL.

Report executed at: 4/22/2022 1:53:42 PM

MCMIS snapshot date: 03/25/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.