

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
VICTORIANOCARRION	AMAURY	C651000862190	FL										
VICTORIANO	AMAURY	C651000862190	FL										
CARRIONVICTORIANO	AMAURY	C651000862190	FL										
CARRION	AMAURY	C651000862190	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		1	Vehicle Inspections:		0	Hazmat Inspections				0			
Driver Out-of-service Inspections:		0	Vehicle Out-of-service Inspections:		0	Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%	Vehicle Out-of-service Rate:		0%	Hazmat Out-of-service Rate:				0%			

Report executed at: 3/13/2023 3:57:21 PM

MCMIS snapshot date: 02/24/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	01/27/2023	1351000	JHI TRANSPORT	CARRION VICTORIANO, AMAURY	C651000862190	FL	06/19/1986	IN	6773001697	N	3	1
Driver Violation: 392.2 Lane Restriction violation NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	Lane Restriction violation								1	0		

The summary counts and rates only include violations that were attributable to VICTORIANOCARRION, AMAURY.

Report executed at: 3/13/2023 3:57:21 PM

MCMIS snapshot date: 02/24/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.