

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
MERCEDCINTRON	JUAN	M623420773350	FL										
MERCED	JUAN	M623420773350	FL										
CINTRONMERCED	JUAN	M623420773350	FL										
CINTRON	JUAN	M623420773350	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 1/26/2024 10:45:13 AM

MCMIS snapshot date: 01/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/19/2021	2828543	ZIGI FREIGHT INC	CINTRON, JUAN	M623420773350	FL	09/15/1977	TN	TC0Q000358	N	3	0
2	10/11/2023	2912492	YUKOV EXPRESS INC	MERCED CINTRON, JUAN	M623420773350	FL	09/15/1977	NY	SPA0334300	N	2	1
Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit								1	0		

The summary counts and rates only include violations that were attributable to MERCEDCINTRON, JUAN.

Report executed at: 1/26/2024 10:45:13 AM

MCMIS snapshot date: 01/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.