

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
MEJIAFAJARDO	JOSE	F263421683750	FL										
MEJIA	JOSE	F263421683750	FL										
FAJARDOMEJIA	JOSE	F263421683750	FL										
FAJARDO	JOSE	F263421683750	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 4/4/2023 1:27:59 PM

MCMIS snapshot date: 02/24/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/26/2022	2629362	CARAVELLA DEMOLITION INC	FAJARDO MEJIA, JOSE	F263421683750	FL	10/15/1968	PA	N621208508	N	1	4
Vehicle Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking NON-OOS Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking Under Vehicle NON-OOS Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking Under Vehicle NON-OOS Vehicle Violation: 393.11 No or defective lighting devices or reflective material as required NON-OOS												
2	08/24/2022	3682825	ADA'S TRANSPORTATION LLC	FAJARDO MEJIA, JOSE (co-driver)	F263421683750	FL	10/15/1968	MS	U038008051	N	1	5
Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS - This violation does NOT apply to FAJARDO MEJIA, JOSE. Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS - This violation does NOT apply to FAJARDO MEJIA, JOSE. Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS - This violation does NOT apply to FAJARDO MEJIA, JOSE. Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS - This violation does NOT apply to FAJARDO MEJIA, JOSE. Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS - This violation does NOT apply to FAJARDO MEJIA, JOSE.												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.45(b)(2)	Brake hose or tubing chafing and/or kinking								3	0		
393.11	No or defective lighting devices or reflective material as required								1	0		

The summary counts and rates only include violations that were attributable to MEJIAFAJARDO, JOSE.

Report executed at: 4/4/2023 1:27:59 PM

MCMIS snapshot date: 02/24/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>