

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
SOMOZA		ALVARO		S520010700900			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			

Report executed at: 11/28/2023 4:18:21 PM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	11/09/2021	3321583	SMART TRUCK	SOMOZA, ALVARO	S520010700900	FL	03/10/1970	AZ	0Y22001982	N	1	5
Vehicle Violation: 393.11 No or defective lighting devices or reflective material as required NON-OOS Vehicle Violation: 393.11 Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.78 Windshield wipers inoperative/defective NON-OOS Vehicle Violation: 390.35 Fraudulent record(s). NON-OOS Vehicle Violation: 390.21T(a) CMV not marked in accordance with regulations NON-OOS												
2	10/05/2022	2828543	ZIGI FREIGHT INC	SOMOZA, ALVARO	S520010700900	FL	03/10/1970	SC	C326001478	N	3	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.11	No or defective lighting devices or reflective material as required								2	0		
393.78	Windshield wipers inoperative/defective								1	0		
390.35	Fraudulent record(s).								1	0		
390.21T(a)	CMV not marked in accordance with regulations								1	0		

The summary counts and rates only include violations that were attributable to SOMOZA, ALVARO.

Report executed at: 11/28/2023 4:18:21 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>