

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name	First Name			License #				State							
MACEOGARCIA	ANDER			42412366				TX							
GARCIAMACEO	ANDER			42412366				TX							
GARCIAMACEO	ANDER			42412366				TX							
GARCIA	ANDER			42412366				TX							
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			

Report executed at: 4/18/2023 12:39:43 PM

MCMIS snapshot date: 03/31/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	02/14/2022	3222886	VIP GLOBAL INC	GARCIA MACEO, ANDER	42412366	TX	05/08/1983	TX	68G80XAFEK	N	2	1
Vehicle Violation: 393.11				Truck-Tractor with No retroreflective sheeting or reflex reflective material on vehicle manufactured after July 1997				NON-OOS				
2	04/28/2022	3222886	VIP GLOBAL INC	GARCIA MACEO, ANDER	42412366	TX	05/08/1983	TX	6AH90SZFHT	N	2	0
3	08/26/2022	3222886	VIP GLOBAL INC	GARCIA MACEO, ANDER	42412366	TX	05/08/1983	TX	6DTH9DGXT7	N	3	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.11	Truck-Tractor with No retroreflective sheeting or reflex reflective material on vehicle manufactured after July 1997								1	0		

The summary counts and rates only include violations that were attributable to MACEOGARCIA, ANDER.

Report executed at: 4/18/2023 12:39:43 PM

MCMIS snapshot date: 03/31/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.