

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
CAMACHOAZUAJE	SIMON	C522781962980	FL										
CAMACHO	SIMON	C522781962980	FL										
AZUAJECAMACHO	SIMON	C522781962980	FL										
AZUAJE	SIMON	C522781962980	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 10/9/2023 5:18:10 PM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/04/2021		RESTORATION HARDWARE	CAMACHO AZUAJE, SIMON	C522781962980	FL	08/18/1996	FL	3253010087	N	1	3
Driver Violation: 392.2 Failure to obey traffic control device NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.95(f) No / insufficient warning devices NON-OOS												
2	03/08/2023	303024	US XPRESS	CAMACHO AZUAJE, SIMON	C522781962980	FL	08/18/1996	IN	9512004593	N	1	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	Failure to obey traffic control device								1	0		
393.9(a)	Inoperable Required Lamp								1	0		
393.95(f)	No / insufficient warning devices								1	0		

The summary counts and rates only include violations that were attributable to CAMACHOAZUAJE, SIMON.

Report executed at: 10/9/2023 5:18:10 PM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.