

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
GILBREATH		FREDDIE		20125732			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		3		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		33%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	09/02/2021	1031258	KELLE'S TRANSPORT SERVICE LLC	GILBREATH, FREDDIE	20125732	TX	04/08/1985	UT	21MA000511	N	3	0			

Report executed at: 6/14/2023 2:09:53 PM

MCMIS snapshot date: 05/26/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	11/08/2022	428823	KNIGHT TRANSPORTATION INC	GILBREATH, FREDDIE	20125732	TX	04/08/1985	CA	NE95002137	N	2	1
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
3	11/09/2022	428823	KNIGHT TRANSPORTATION INC	GILBREATH, FREDDIE	20125732	TX	04/08/1985	CA	UD89001826	N	2	0
4	11/15/2022	428823	KNIGHT TRANSPORTATION INC	GILBREATH, FREDDIE	20125732	TX	04/08/1985	KS	HP00330441	N	2	0
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.75(a)(3)		Tire-flat and/or audible air leak							1		1	

The summary counts and rates only include violations that were attributable to GILBREATH, FREDDIE.

Report executed at: 6/14/2023 2:09:53 PM

MCMIS snapshot date: 05/26/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.