PSP Detailed Report

Federal Motor Carrier Safety Administration

	Driver Information																	
Last Name First Name					License #						State							
PEREZ ALFREDO					FREDO	L116000800281						FL						
LEYVAPEREZ ALFREDO					ALFREDO			L116000800281					FL					
LEYVA ALFREDO					FREDO	L116000800281						FL						
	Crash Activity																	
Cra	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
	# of Crashes:					# of Crashes with Fata	alities:	0			# of Crash	es with l	njuries:	0	# of Tow			1
	# Not preventable: 0				# of Fatalit					# of 1			njuries:	0	# of Hazmat Rele			0
Cra	Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
	Date DOT # Carr			ier N	ame	Driver Name		Driver Lic		State	Driver DOB	Rpt St	Report Number		Location	# Fatalities	# of Injuries	
1	12/08/2021	3660559				ALFREDO, LEYVA	L1 ⁻	L116000800281		FL	01/28/1980	WV	WV202129909A		I-79 MP 84	0	0	
	Inspection Activity (3 year history from MCMIS snapshot date)																	
Insp	ection Sum	nary																
Driver Summary						Vehicle Summary					Hazmat Summary							
Driver Inspections: 6					Vehicle Inspections:				2 H	Pazmat Inspections						0		
Driver Out-of-service Inspections:					1	1 Vehicle Out-of-service Inspections:					1 H	Hazmat Out-of-service Inspections: 0						
Driver Out-of-service Rate:					17%	Vehicle Out-of-service Rate:				50% H	Hazmat Out-of-service Rate: 0%							

Report executed at: 7/14/2023 3:02:20 PM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrie	er Info			Driver Info	Inspection Info							
	Date	DOT # Carrier Name		Driver Name Driver Lic		State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	11/28/2021	3213032	HERSUA TRANSPORT CORP	LEYVA PEREZ, ALFREDO	L116000800281	FL	01/28/1980	UT	22TD000079	N	3	0
2	12/08/2021	/08/2021 3660559 US TRUCKING EXPERTS LLC		LEYVA PEREZ, ALFREDO	L116000800281	FL	01/28/1980	WV	4722000097	N	2	0
3	02/06/2022	3417412	KINGS CROWN LLC	LEYVA PEREZ, ALFREDO	L116000800281	FL	01/28/1980	NM	2917M11PJR	N	3	0
4	02/25/2022	3417412	KINGS CROWN LLC	LEYVA PEREZ, ALFREDO	L116000800281	FL	01/28/1980	IN	9109000725	N	3	2
	Driver Vi Driver Vi		Jimit.	/Local Laws - Speeding 11-14 miles per hour over the speed NON-OOS r failing to retain previous 7 days records of duty status OOS								
5	06/25/2022	06/25/2022 1975822 PRO INTERMODAL LLC		LEYVA-PEREZ, ALFREDO L116000800281 FL 01		01/28/1980	FL	1795004903	Ν	3	0	
6	03/07/2023	1975822	PRO INTERMODAL LLC	LEYVA PEREZ, ALFREDO	L116000800281	FL	01/28/1980	GA	1409000427	N	1	1
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
Violat	ion Summary	,										
Violation #				# of Violati	# of Violations		# of Out-of-service Violations					
393.75	(a)(3)	Tire-flat and/o	or audible air leak		1		1					
392.2		State/Local L	aws - Speeding 11-14 miles per		1		0					
395.8(k)(2)		Driver failing	to retain previous 7 days record		1		1					

The summary counts and rates only include violations that were attributable to PEREZ, ALFREDO.

Report executed at: 7/14/2023 3:02:20 PM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.