

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
AYALAHERRERA		LEONARDO		39029237			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		1		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			

Report executed at: 7/24/2023 9:52:13 AM

MCMIS snapshot date: 06/30/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	01/30/2023	3434290	IQS GROUP LLC	AYALA HERRERA , LEONARDO	39029237	TX	05/21/1977	CO	PF10303642	N	2	4
<div>Driver Violation: 395.24(c)(2)(iii) Driver failed to manually add shipping document number NON-OOS</div> <div>Vehicle Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking NON-OOS</div> <div>Vehicle Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking NON-OOS</div> <div>Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS</div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
395.24(c)(2)(iii)	Driver failed to manually add shipping document number								1	0		
393.45(b)(2)	Brake hose or tubing chafing and/or kinking								2	0		
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998								1	0		

The summary counts and rates only include violations that were attributable to AYALAHERRERA, LEONARDO.

Report executed at: 7/24/2023 9:52:13 AM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>