

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
PEREZFERNANDEZ		FERNANDO		P621240651900			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		9		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		25%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	09/13/2020	3270809	BG CARGO LOGISTIC INC	PEREZ FERNANDEZ, FERNANDO	P621240651900	FL	05/30/1965	PA	C1E2025762	N	3	0			
2	09/18/2020	3270809	BG CARGO LOGISTICS INC	PEREZ FERNANDEZ, FERNANDO	P621240651900	FL	05/30/1965	NM	3248121414	N	3	0			

Report executed at: 7/24/2023 11:50:13 AM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

3	05/15/2021	2951971	CARGO TRANSPORT ALLIANCE LLC	PEREZ FERNANDEZ, FERNANDO	P621240651900	FL	05/30/1965	CA	NDTI002269	N	1	0
4	08/02/2021	2951971	CARGO TRANSPORT ALLIANCE LLC	PEREZ FERNANDEZ, FERNANDO	P621240651900	FL	05/30/1965	WA	W614004885	N	2	0
5	08/17/2021	3619396	JCROX ABELLA LLC	PEREZ, FERNANDO	P621240651900	FL	05/30/1965	TX	63FA0XAFZO	N	2	3
Vehicle Violation: 396.3(a)(1) Brake system pressure loss OOS Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories OOS Vehicle Violation: 393.45(d) Brake Connections with Leaks Under Vehicle NON-OOS												
6	06/18/2022	3030718	MXC	FERNANDEZ, FERNANDO	P621240651900	FL	05/30/1965	NC	0006428965	N	3	0
7	09/13/2022	3030718	MIG XPRESS CORP	PEREZ FERNANDEZ, FERNANDO	P621240651900	FL	05/30/1965	KS	HP93061285	N	3	0
8	09/14/2022	3030718	MXC	PEREZ, FERNANDO	P621240651900	FL	05/30/1965	IN	9090000036	N	3	1
Driver Violation: 392.2 State/Local Laws - Speeding 11-14 miles per hour over the speed limit. NON-OOS												
9	11/18/2022	2136700	TEXSTAR OILFIELD SERVICES LLC	PEREZ, FERNANDO	P621240651900	FL	05/30/1965	TX	6G590XRQIE	N	2	6
Vehicle Violation: 390.21(c) Improper size, location, or color of CMV marking NON-OOS Vehicle Violation: 390.21(c) Improper size, location, or color of CMV marking NON-OOS Vehicle Violation: 393.9(a) Inoperable head lamps NON-OOS Vehicle Violation: 393.11 Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS												
<b>Violation Summary</b>												
Violation #	Description								# of Violations	# of Out-of-service Violations		
396.3(a)(1)	Brake system pressure loss								2	2		
393.45(d)	Brake Connections with Leaks Under Vehicle								1	0		
392.2	State/Local Laws - Speeding 11-14 miles per hour over the speed limit.								1	0		
390.21(c)	Improper size, location, or color of CMV marking								2	0		
393.9(a)	Inoperable head lamps								3	0		

Report executed at: 7/24/2023 11:50:13 AM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	1	0
--------	---	---	---

The summary counts and rates only include violations that were attributable to PEREZFERNANDEZ, FERNANDO.

Report executed at: 7/24/2023 11:50:13 AM

MCMIS snapshot date: 06/30/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.