PSP Detailed Report

Federal Motor Carrier Safety Administration

| Driver Information | | | | | | | | | | | | | | | | | | | | |
|---|--|---|-------------|--------------|-------------|--|---------|---------------|--|---------|-----------|-------------------------|------------------------------------|-----------------|---------------|--------|----------------|---------|--------------|--|
| Last Name First Name | | | | | | License # | | | | | | | State | | | | | | | |
| QASEM ANIS | | | | | | 000030678406 | | | | | | NC | NC | | | | | | | |
| Crash Activity | | | | | | | | | | | | | | | | | | | | |
| Crash | Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | | | | | |
| # of Crashes: 0 | | | | | | # of Crashes with Fatalities: 0 # of C | | | | | Crashes w | rashes with Injuries: 0 | | | | | # of Towaways: | | | |
| # Not preventable: 0 | | | | | | # of Fata | 0 | | | | # | of Injuri | es : 0 | # of Hazmat Rel | | | eleases | : 0 | | |
| Crash | Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | | | | | |
| | Date DOT # Carrier | | | Name | Driver Name | | | Driver Lic St | | | Drive | r DOB Rp | St Re | port Nur | mber Location | on #Fa | atalities | # of In | Injuries | |
| | | | | | | | | | | | | | | | | | | | | |
| Inspection Activity (3 year history from MCMIS snapshot date) | | | | | | | | | | | | | | | | | | | | |
| Inspection Summary | | | | | | | | | | | | | | | | | | | | |
| Driver Summary | | | | | | Vehicle Summary | | | | | | Hazmat Summary | | | | | | | | |
| Driver | Inspections: | | | | 3 \ | /ehicle Inspections: | | | | 1 Hazma | Inspec | tions | ıs | | | | 0 | | | |
| Driver | Out-of-servi | ce Inspections: | | | 0 \ | /ehicle Out-of-service In | spectio | ections: 1 | | | | 1 Hazma | Hazmat Out-of-service Inspections: | | | | | | 0 | |
| Driver | Out-of-servi | -of-service Inspections: 0 Vehicle Out-of-service -of-service Rate: 0% Vehicle Out-of-service | | | | | ate: | | | | 10 | 00% Hazma | t Out-of | -service | Rate: | | | | 0% | |
| Inspection Details | | | | | | | | | | | | | | | | | | | | |
| Carrier Info Driver I | | | | | | nfo | | | | | | Inspection Info | | | | | | | | |
| Date | | DOT# | Carrier N | Carrier Name | | Driver Name | | Driver Li | | | State | Driver DOI | B Rpt St | St R | eport Number | Hazma | t Insp | | # of Viol | |
| | | | | | | | | | | | | | | | Insp | | | VIOI | | |
| 1 | 10/12/202 | 1 246204 | SMITH TRANS | PORT INC | QASEM, | A, ANIS | | 0000306784 | |)6 | NC 02/0 | | 2/09/1987 NC | | 0006350880 | | | 3 | 0 | |
| | | | | | | | | | | | | | | | | | | | | |

Report executed at: 8/8/2023 1:04:27 PM MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| | | | | _ | | | | | | | | | |
|--|---|-------------------------------|---------------------|-------------|--------------|----|------------|----|------------|-----------------|-----|-----------------------------------|--|
| 2 | 02/09/2022 | 246204 | SMITH TRANSPORT INC | QASEM, ANIS | 000030678406 | NC | 02/09/1987 | TN | TESE000387 | N | 3 | 2 | |
| | Driver Violation: 392.2 Failure to Maintain Lane NON-OOS | | | | | | | | | | | | |
| | Driver Violation: 390.17 Operating a CMV while texting NON-OOS | | | | | | | | | | | | |
| 3 | 07/29/2022 | 2977626 | NSO EXPRESS LLC | QASEM, ANIS | 000030678406 | NC | 02/09/1987 | CA | UG6L002533 | N | 2 | 2 | |
| | Vehicle Violation: 392.9(a)(1) Failing to secure cargo as specified in 49 CFR 393.100 through OOS 393.142 | | | | | | | | | | | | |
| | Vehicle Violation: 393.126(c)(2) All corners of loaded intermodal container not secured when transported on vehicle other than container chassis vehicle | | | | | | | | | | | | |
| Violation Summary | | | | | | | | | | | | | |
| Violation # | | Description | | | | | | | | # of Violations | | # of Out-of-service Violations | |
| 392.2 Failure to Maintain Lane | | | | | | | | | | 1 | | 0 | |
| 390.17 | | Operating a CMV while texting | | | | | | | | | . 0 | | |
| 392.9(a)(1) Failing to secure cargo as specified in 49 CFR 393.100 through 393.142 | | | | | | | | | | 1 | | 1 | |
| 393.126 | 93.126(c)(2) All corners of loaded intermodal container not secured when transported on vehicle other than container chassis vehicle | | | | | | | | | 1 | | 1 | |

The summary counts and rates only include violations that were attributable to QASEM, ANIS.

Report executed at: 8/8/2023 1:04:27 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.