

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
GONZALEZRODRIGUEZ		GONZALEZ		G524880860120		FL									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	Fatalities	# of Injuries				
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		3		Hazmat Inspections						0	
Driver Out-of-service Inspections:		2		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:						0	
Driver Out-of-service Rate:		50%		Vehicle Out-of-service Rate:		33%		Hazmat Out-of-service Rate:						0%	
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol				
1 06/15/2022	3090283	TERGLAU INC	GONZALEZ RODRIGUEZ, WILFREDO	G524880860120	FL	01/12/1986	OR	AASY001783	N	3	3				
Driver Violation:		395.8(e)(1)		False report of drivers record of duty status		OOS									
Driver Violation:		395.8(e)(1)		False report of drivers record of duty status		OOS									
Driver Violation:		395.8(e)(1)		False report of drivers record of duty status		OOS									

Report executed at: 8/18/2023 8:39:06 AM
MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/2redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	11/10/2022	3090283	TERGLAU INC	WILFREDO, GONZALEZ	G524880860120	FL	01/12/1986	TN	TEQM006876	N	1	5
	Vehicle Violation:	393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition									
	Vehicle Violation:	393.47(e)	Clamp or Roto type brake out-of-adjustment									
	Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear									
	Vehicle Violation:	396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination									
	Driver Violation:	395.8(e)(1)	False report of drivers record of duty status									
3	04/15/2023	3090283	TERGLAU INC	GONZALEZ, WILFREDO	G524880860120	FL	01/12/1986	TX	6K980VBJF3	N	2	6
	Vehicle Violation:	393.47(e)	Clamp or Roto type brake out-of-adjustment									
	Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear									
	Vehicle Violation:	393.9(a)	Inoperative turn signal									
	Vehicle Violation:	393.9(a)	Inoperative turn signal									
	Vehicle Violation:	393.9(a)	Inoperable Required Lamp									
	Vehicle Violation:	393.60(d)	Glazing permits < 70% of light									
4	07/13/2023	3090283	TERGLAU INC	GONZALEZ RODRIGUEZ, WILFREDO	G524880860120	FL	01/12/1986	FL	3660008310	N	2	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
395.8(e)(1)	False report of drivers record of duty status								4	4		
393.47(e)	Clamp or Roto type brake out-of-adjustment								2	0		
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear								2	0		
393.9(a)	Inoperative turn signal								3	0		
393.60(d)	Glazing permits < 70% of light								1	0		
393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition								1	0		
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination								1	1		

The summary counts and rates only include violations that were attributable to GONZALEZRODRIGUEZ, GONZALEZ.

Report executed at: 8/18/2023 8:39:06 AM
MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/2redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.