

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
GONZALEZRODRIGUEZ		GONZALEZ		G524880860120		FL									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:				5		Vehicle Inspections:				4		Hazmat Inspections		0	
Driver Out-of-service Inspections:				2		Vehicle Out-of-service Inspections:				1		Hazmat Out-of-service Inspections:		0	
Driver Out-of-service Rate:				40%		Vehicle Out-of-service Rate:				25%		Hazmat Out-of-service Rate:		0%	
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	06/15/2022	3090283	TERGLAU INC	GONZALEZ RODRIGUEZ, WILFREDO	G524880860120	FL	01/12/1986	OR	AASY001783	N	3	3			
Driver Violation:				395.8(e)(1)		False report of drivers record of duty status		OOS							
Driver Violation:				395.8(e)(1)		False report of drivers record of duty status		OOS							
Driver Violation:				395.8(e)(1)		False report of drivers record of duty status		OOS							

Report executed at: 4/16/2024 5:12:02 PM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	11/10/2022	3090283	TERGLAU INC	WILFREDO, GONZALEZ	G524880860120	FL	01/12/1986	TN	TEQM006876	N	1	5
Vehicle Violation:		393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition			NON-OOS						
Vehicle Violation:		393.47(e)	Clamp or Roto type brake out-of-adjustment			NON-OOS						
Vehicle Violation:		393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear			NON-OOS						
Vehicle Violation:		396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination			OOS						
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status			OOS						
3	04/15/2023	3090283	TERGLAU INC	GONZALEZ, WILFREDO	G524880860120	FL	01/12/1986	TX	6K980VBJF3	N	2	6
Vehicle Violation:		393.47(e)	Clamp or Roto type brake out-of-adjustment			NON-OOS						
Vehicle Violation:		393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperative turn signal			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperative turn signal			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.60(d)	Glazing permits < 70% of light			NON-OOS						
4	07/13/2023	3090283	TERGLAU INC	GONZALEZ RODRIGUEZ, WILFREDO	G524880860120	FL	01/12/1986	FL	3660008310	N	2	0
5	11/03/2023	1437731	STAR TRANSPORTATION PA INC	GONZALEZ RODRIGUEZ, WILFREDO	G524880860120	FL	01/12/1986	NM	6240N8J3TT	N	1	0

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.47(e)	Clamp or Roto type brake out-of-adjustment	2	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	2	0
393.9(a)	Inoperative turn signal	3	0
393.60(d)	Glazing permits < 70% of light	1	0
395.8(e)(1)	False report of drivers record of duty status	4	4
393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition	1	0
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	1	1

The summary counts and rates only include violations that were attributable to GONZALEZRODRIGUEZ, GONZALEZ.

Report executed at: 4/16/2024 5:12:02 PM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>