

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
MERINOCAMPOS	JULIO	47369338	TX										
MERINOCAMPOS	JULIO	47369338	TX										
MERINO	JULIO	47369338	TX										
CAMPOS	JULIO	47369338	TX										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		4		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 11/9/2022 11:02:33 AM

MCMIS snapshot date: 10/28/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/01/2022	2119331	EFFICIENT MOTOR FREIGHT INC	MERINO CAMPOS, JULIO	47369338	TX	12/31/1983	NM	9520M1O6ST	N	2	0
2	08/20/2022	16130	RYDER TRUCK RENTAL INC	MERINO CAMPOS, JULIO	47369338	TX	12/31/1983	CA	UEX2002145	N	3	0
3	09/30/2022	16130	RYDER TRUCK RENTAL INC	MERINO CAMPOS, JULIO	47369338	TX	12/31/1983	CA	UC7V001052	N	3	1
Vehicle Violation: 396.7      Unsafe operations forbidden      NON-OOS												
4	10/08/2022	3508157	JMZ EXPRESS INC	MERINO CAMPOS, JULIO	47369338	TX	12/31/1983	OR	AABU005663	N	3	2
Driver Violation: 392.2      State Operating Authority violation      NON-OOS Vehicle Violation: 390.21T(b)      Carrier name and/or USDOT Number not displayed as required      NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	State Operating Authority violation								1	0		
390.21T(b)	Carrier name and/or USDOT Number not displayed as required								1	0		
396.7	Unsafe operations forbidden								1	0		

The summary counts and rates only include violations that were attributable to MERINOCAMPOS, JULIO.

Report executed at: 11/9/2022 11:02:33 AM

MCMIS snapshot date: 10/28/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>