

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
VAZQUEZ		WILSON		40625868		TX									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		1	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	03/20/2021	2443366	RNDY TRANSPORT INC	Vazquez, Wilson	40625868	TX	12/31/1979	CT	CT2100112344	84-W-59	0	0			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		7		Vehicle Inspections:		5		Hazmat Inspections				1			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	06/17/2021	2443366	RNDY TRANSPORT INC	VAZQUEZ, WILSON	40625868	TX	12/31/1979	TX	61QF0VBFGV	N	2	2			
Vehicle Violation:		393.78		Windshield wipers inoperative/defective		NON-OOS									
Driver Violation:		393.95(a)		No/discharged/unsecured fire extinguisher		NON-OOS									

Report executed at: 8/10/2023 12:38:45 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	06/23/2021	2443366	RNDY TRANSPORT INC	VAZQUEZ, WILSON	40625868	TX	12/31/1979	MN	0ADO002123	N	2	1
Vehicle Violation:			393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997		NON-OOS						
3	02/17/2022	2443366	RNDY TRANSPORT INC	VAZQUEZ, WILSON	40625868	TX	12/31/1979	IA	000TT76X8K	N	3	0
4	05/06/2022	2443366	RNDY TRANSPORT INC	CRUZ VAZQUEZ, WILSON	40625868	TX	12/31/1979	TN	TCJW005718	N	2	1
Vehicle Violation:			392.2	State or International Fuel Tax (IFTA) Violation		NON-OOS						
5	12/06/2022	2443366	RNDY TRANSPORT INC	VAZQUEZ, WILSON	40625868	TX	12/31/1979	TX	6GN90AMV6E	Y	2	0
6	06/19/2023		MCCOURT CONSTRUVTION INC	VAZQUEZ, WILSON	40625868	TX	12/31/1979	FL	2545004158	N	3	0
7	06/19/2023	2999600	DIAMOND HAULING INC	VAZQUEZ, WILSON	40625868	TX	12/31/1979	FL	2545004156	N	2	2
Vehicle Violation:			390.21T(c)	Improper size, location, or color of CMV marking		NON-OOS						
Vehicle Violation:			393.104(b)	Damaged securement system/tiedowns		NON-OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.78		Windshield wipers inoperative/defective							1		0	
393.95(a)		No/discharged/unsecured fire extinguisher							1		0	
393.11		Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997							1		0	
390.21T(c)		Improper size, location, or color of CMV marking							1		0	
393.104(b)		Damaged securement system/tiedowns							1		0	
392.2		State or International Fuel Tax (IFTA) Violation							1		0	

The summary counts and rates only include violations that were attributable to VAZQUEZ, WILSON.

Report executed at: 8/10/2023 12:38:45 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>