

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
SANTIESTEBANMACHADO	HERNAN	S532325641480	FL										
SANTIESTEBAN	HERNAN E	S532325641480	FL										
MACHADO	HERNAN E	S532325641480	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		1	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		1	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		1	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	05/22/2021	2415345	G&A EXPRESS TRANSPORT LLC	SANTIESTEBAN, HERNAN	S532325641480	FL	04/28/1964	TX	TX6169HQE137	NOT REPORTED	0	1	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%	

Report executed at: 8/24/2023 4:11:19 PM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/22/2021	2415345	G&A EXPRESS TRANSPORT LLC	SANTIESTEBAN MACHADO, HERNAN	S532325641480	FL	04/28/1964	CA	NC2K003073	N	1	7
Vehicle Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking NON-OOS Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories NON-OOS Vehicle Violation: 396.3(a)(1) Brakes (general) Explain: NON-OOS Vehicle Violation: 393.75(a)(1) Tire-ply or belt material exposed NON-OOS Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS Vehicle Violation: 393.48(a) Inoperative/defective brakes OOS Vehicle Violation: 393.48(a) Inoperative/defective brakes OOS												
2	05/29/2021	2415345	G&A EXPRESS TRANSPORT LLC	SANTESTEBAN MACHADO, HERNAN	S532325641480	FL	04/28/1964	TN	TEYK002176	N	1	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.45(b)(2)	Brake hose or tubing chafing and/or kinking								1	0		
396.3(a)(1)	Inspection, repair and maintenance of parts & accessories								2	0		
393.75(a)(1)	Tire-ply or belt material exposed								1	0		
393.45	Brake tubing and hose adequacy								1	1		
393.48(a)	Inoperative/defective brakes								2	2		

The summary counts and rates only include violations that were attributable to SANTIESTEBANMACHADO, HERNAN.

Report executed at: 8/24/2023 4:11:19 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>