PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																			
Last Name First Name					License #						State								
CEDENO ALEJANDRO					C350013931860						FL								
	Crash Activity																		
Crash	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																		
# of Crashes: 0					# of Crashes with Fatalities: 0 # of C				Crashes	rashes with Injuries: 0				# of Towaways:					
# Not preventable:				# of Fatalit				0 # of				# of li	njuries:	: 0 # of Hazmat Relea			leases: 0		
Crash	Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																		
	Date	DOT#	Carrie	Name		Driver Name	Dr	Driver Lic State Drive			Drive	r DOB	Rpt St	Rpt St Report Number			# Fat	alities	# of Injuries
	Inspection Activity (3 year history from MCMIS snapshot date)																		
Inspe	Inspection Summary																		
Driver Summary					Vehicle Summary						Hazmat Summary								
Driver Inspections:				1	Vehicle Inspections:		1				1 Haz	1 Hazmat Inspections							
Driver Out-of-service Inspections:					0	Vehicle Out-of-service Ins	spection	ections: 1				1 Haz	Hazmat Out-of-service Inspections:						
Driver Out-of-service Rate:				0%	Vehicle Out-of-service Rate:					100% Hazmat Out-of-service				vice Rate	ice Rate:				
Inspection Details																			
Carrier Info Driver					Driver	Info							Inspection Info						
Date D		DOT#	Carrier Name			Driver Name		Driver Li		State D		Driver	iver DOB Rpt St		Report Number		Hazmat Insp	Insp L	evel # of Viol
																			1.0.
1	10/07/202	2890110	C1 TRANSPOR	RTATION INC	CEDEN	ENO, ALEJANDRO		C350013931860		60	FL	05/26/	1993	ID	1700	003237	N	2	1
	Vehicle Violation: 393.9(a) Inoperative Brake Lamps OOS																		

Report executed at: 8/28/2023 1:05:40 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary	/iolation Summary									
Violation #	Description	# of Violations	# of Out-of-service Violations							
393.9(a)	Inoperative Brake Lamps	1	1							

The summary counts and rates only include violations that were attributable to CEDENO, ALEJANDRO.

Report executed at: 8/28/2023 1:05:40 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.