

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
ALI		ABDIRAHMAN		N034133738807			MN								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 11/2/2023 9:29:27 AM

MCMIS snapshot date: 09/29/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	01/14/2022	2907429	SILK WAY TRANSPORT INC	ALI, ABDIRAHMAN	N034133738807	MN	01/01/1997	AZ	0YAO004763	N	1	5
Vehicle Violation: 393.45(a) Air Brake tubing improperly joined or spliced OOS Vehicle Violation: 393.9(a) Inoperable tail lamp NON-OOS Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS Vehicle Violation: 393.201(a) Frame cracked / loose / sagging / broken OOS												
2	02/01/2022	2907429	SILK WAY TRANSPORT INC	ALI, ABDIRAHMAN	N034133738807	MN	01/01/1997	CA	NDVC001974	N	1	9
Vehicle Violation: 393.201(a) Frame cracked / loose / sagging / broken OOS Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove OOS Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS Vehicle Violation: 392.2 Violation of Local Laws - Explain: NON-OOS Vehicle Violation: 392.2 Violation of Local Laws - Explain: NON-OOS Vehicle Violation: 392.2 State Operating Authority violation NON-OOS Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories NON-OOS Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit NON-OOS												
3	09/12/2022	1730271	A F F TRANS LLC	ALI, ABDIRAHMAN	N034133738807	MN	01/01/1997	WI	2280013399	N	3	1
Vehicle Violation: 392.2 Excessive Weight violation NON-OOS												
4	08/17/2023	2828543	ROYAL3 INC	ALI, ABDIRAHMAN	N034133738807	MN	01/01/1997	VA	5443011155	N	3	1
Driver Violation: 392.2 Unlawfully parking and/or leaving vehicle in the roadway NON-OOS												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.45(a)		Air Brake tubing improperly joined or spliced							1		1	
393.9(a)		Inoperable tail lamp							1		0	

Report executed at: 11/2/2023 9:29:27 AM

MCMIS snapshot date: 09/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	3	1
393.201(a)	Frame cracked / loose / sagging / broken	2	2
392.2	Unlawfully parking and/or leaving vehicle in the roadway	5	0
393.45	Brake tubing and hose adequacy	1	1
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
396.3(a)(1)	Inspection, repair and maintenance of parts & accessories	1	0
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit	1	0

The summary counts and rates only include violations that were attributable to ALI, ABDIRAHMAN.

Report executed at: 11/2/2023 9:29:27 AM

MCMIS snapshot date: 09/29/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.