

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
LANUZA	GASPAR	G524280661801	FL										
GONZALEZLANUZA	GASPAR	G524280661801	FL										
GONZALEZ	GASPAR	G524280661801	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		1	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		1		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	07/04/2019	3090283	TERGLAU INC	GONZALEZ LANUZA, GASPAR	G524280661801	FL	05/20/1966	SC	SC0019590832	RAPIDS CT	0	0	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		4		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%	

Report executed at: 8/28/2023 5:17:55 PM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	01/17/2021	2379727	BEST 3 LOGISTICS INC	GONZALEZ LANUZA, GASPAR	G524280661801	FL	05/20/1966	WA	W428002521	N	2	1
Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS												
2	07/06/2021	2379727	BEST 3 LOGISTICS INC	GONZALEZ, GASPAR	G524280661801	FL	05/20/1966	SD	0010039803	N	2	1
Vehicle Violation: 393.9(a) Inoperative Brake Lamps OOS												
3	03/09/2022	2379727	BEST 3 LOGISTICS INC	GONZALEZ LANUZA, GASPAR	G524280661801	FL	05/20/1966	MO	00SH005616	N	3	0
4	03/21/2023	3187195	MILSPED FREIGHT LLC	GONZALEZ LANUZA, GASPAR	G524280661801	FL	05/20/1966	NY	SPG0214296	N	3	2
Driver Violation: 392.2 Failure to obey traffic control device NON-OOS												
Vehicle Violation: 392.2 State or International Fuel Tax (IFTA) Violation NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	State vehicle registration or License Plate violation								3	0		
393.9(a)	Inoperative Brake Lamps								1	1		

The summary counts and rates only include violations that were attributable to LANUZA, GASPAR.

Report executed at: 8/28/2023 5:17:55 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>