

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name	First Name			License #			State								
PARRAFONSECA	NESTOR			P615639630150			FL								
PARRA	NESTOR			P615639630150			FL								
FONSECA	NESTOR			P615639630150			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		1	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	02/20/2019	1845140	SCS LOGISTICS LLC	PARRA FONSECA, NESTOR	P615639630150	FL	01/15/1963	MD	MD19A0558442	CATOCTIN MOUNTAIN HWY	0	0			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 9/5/2023 7:45:38 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/25/2021	2270003	J LION TRANSPORT LLC	PARRA FONSECA, NESTOR YOBANY	P615639630150	FL	01/15/1963	TN	TCKA000879	N	3	0
2	04/21/2022	2270003	J LION	PARRA FONSECA, NESTOR	P615639630150	FL	01/15/1963	MO	0692000129	N	3	0
3	05/19/2023	2270003	J LION	PARRA FONSECA, NESTOR YOBANY	P615639630150	FL	01/15/1963	NC	0006536964	N	2	17
<div>Driver Violation: 392.2 State or International Fuel Tax (IFTA) Violation NON-OOS</div> <div>Driver Violation: 392.7(a) Driver failing to conduct pre-trip inspection NON-OOS</div> <div>Driver Violation: 392.8 Failing to inspect/use emergency equipment NON-OOS</div> <div>Driver Violation: 395.30(b)(1) Driver failed to certify the accuracy of the information gathered by the ELD NON-OOS</div> <div>Vehicle Violation: 392.2 IRP Apportioned Tag or Registration Violation NON-OOS</div> <div>Vehicle Violation: 393.19 Inoperative/Defective Hazard Warning Lamp NON-OOS</div> <div>Vehicle Violation: 393.19 Inoperative/Defective Hazard Warning Lamp NON-OOS</div> <div>Vehicle Violation: 393.203(e) Cab front bumper missing/unsecured/protrude NON-OOS</div> <div>Vehicle Violation: 393.75(a) Flat tire or fabric exposed OOS</div> <div>Vehicle Violation: 393.75(c) Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread grooves 3 separate locations 8 inches apart OOS</div> <div>Vehicle Violation: 393.75(c) Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread grooves 3 separate locations 8 inches apart OOS</div> <div>Vehicle Violation: 393.78 Windshield wipers inoperative/defective NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS</div> <div>Vehicle Violation: 393.95(a) No/discharged/unsecured fire extinguisher NON-OOS</div> <div>Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperative turn signal OOS</div>												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		State or International Fuel Tax (IFTA) Violation							2		0	

Report executed at: 9/5/2023 7:45:38 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

392.7(a)	Driver failing to conduct pre-trip inspection	1	0
392.8	Failing to inspect/use emergency equipment	1	0
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	1	0
393.19	Inoperative/Defective Hazard Warning Lamp	2	0
393.203(e)	Cab front bumper missing/unsecured/protrude	1	0
393.75(a)	Flat tire or fabric exposed	1	1
393.75(c)	Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread grooves 3 separate locations 8 inches apart	2	2
393.78	Windshield wipers inoperative/defective	1	0
393.9(a)	Inoperative turn signal	3	1
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0

The summary counts and rates only include violations that were attributable to PARRAFONSECA, NESTOR.

Report executed at: 9/5/2023 7:45:38 PM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.