

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RAMONESPINOSA	JUAN RAMON	E215436640980	FL										
RAMON	JUAN RAMON	E215436640980	FL										
ESPINOSARAMON	JUAN RAMON	E215436640980	FL										
ESPINOSA	JUAN	E215436640980	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		9		Vehicle Inspections:		5		Hazmat Inspections				0	
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		4		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		11%		Vehicle Out-of-service Rate:		80%		Hazmat Out-of-service Rate:				0%	

Report executed at: 9/8/2023 12:16:58 PM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	02/15/2021	3063897	CIRCLE O INC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	MA	CR00000924	N	3	0
2	04/03/2021	3063897	CIRCLE O INC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	AL	JPCP006327	N	2	1
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak				OOS				
3	04/15/2021	3063897	CIRCLE O INC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	IL	4050730174	N	3	0
4	04/23/2021	3063897	CIRCLE O INC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	WI	2641005210	N	2	2
Vehicle Violation: 392.2				Excessive Weight violation				NON-OOS				
Vehicle Violation: 392.9(a)				Failing to secure load				OOS				
5	10/05/2021	3054867	TEGA TRANSPORT INC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	MO	W210002133	N	3	0
6	08/18/2022	3054867	TEGA TRANSPORT INC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	TN	TEQM006634	N	1	3
Vehicle Violation: 392.2				IRP Apportioned Tag or Registration Violation				NON-OOS				
Vehicle Violation: 392.9(a)(2)				Failing to secure vehicle equipment				OOS				
Vehicle Violation: 392.2				Dimension Violation (Width / Height / Length)				NON-OOS				
7	11/30/2022	2515919	OTR EXPRESS INC	ESPINNOSA, JUAN	E215436640980	FL	03/18/1964	FL	3252011327	N	3	0
8	06/24/2023	3724904	PL TRANS INC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	CA	ND64006821	N	1	1
Vehicle Violation: 393.45(d)				Brake connections with leaks or constrictions				NON-OOS				
9	08/10/2023	3267070	UNITED BROTHERS SERVICES LLC	ESPINOSA, JUAN	E215436640980	FL	03/18/1964	CA	ND7U006838	N	1	3
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak				OOS				
Vehicle Violation: 396.5(b)				Hubs - oil and/or Grease Leaking from hub - outer wheel				OOS				
Driver Violation: 395.8(e)(1)				False report of drivers record of duty status				OOS				

Report executed at: 9/8/2023 12:16:58 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	IRP Apportioned Tag or Registration Violation	3	0
392.9(a)(2)	Failing to secure vehicle equipment	1	1
393.75(a)(3)	Tire-flat and/or audible air leak	2	2
396.5(b)	Hubs - oil and/or Grease Leaking from hub - outer wheel	1	1
395.8(e)(1)	False report of drivers record of duty status	1	1
392.9(a)	Failing to secure load	1	1
393.45(d)	Brake connections with leaks or constrictions	1	0

The summary counts and rates only include violations that were attributable to RAMONESPINOSA, JUAN RAMON.

Report executed at: 9/8/2023 12:16:58 PM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.