PSP Detailed Report

Federal Motor Carrier Safety Administration

						Driv	er Info	orm	ation											
Last Na	ame		F	rst Name			Licer	nse #	ŧ					State						
SANCROFT ROMAINE							S526	67279	942060					FL						
	Crash Activity																			
Crash	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
# of Crashes: 0						# of Crashes with Fatalities: 0					# of Crashes with Injuries: 0					# of Towaways: 0				
# Not preventable: 0						# of Fata	alities:	0					# of I	njuries:	0	0 # of Hazmat Re			ises: 0	
Crash	Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
	Date DOT# Carrie			Name	Driver Name			Driver Lic S			Drive	r DOB	Rpt St	Report	Report Number		# Fata	lities #	of Injuries	
					Insped	ction Activity (3 year	r histo	ry f	rom MCM	IS sn	apsho	ot date)								
Inspe	ction Sumn	nary																		
Driver Summary						Vehicle Summary							Hazmat Summary							
Driver Inspections:					2	Vehicle Inspections: 2					2 Haz	Hazmat Inspections								
Driver	Out-of-servi	ce Inspections:			0	Vehicle Out-of-service In	spection	ns:				0 Haz	mat O	ut-of-serv	vice Inspe	ections:			0	
Driver Out-of-service Rate:					0%	Vehicle Out-of-service Ra	0% Hazm				mat Out-of-service Rate:						0%			
Inspection Details																				
Carrier Info Driver						Info							Inspection Info							
Date DOT #		Carrier I	er Name		Driver Name		Driver L			State	Driver	iver DOB	Rpt St	Report N	Number I	Hazmat Insp	Insp Lev	el # of Viol		
1	02/15/202	3 315503	TRANSAM TRU	ICKING INC	ROFT, ROMAINE		S526727942060		60	FL 06/06/1994		1994	TN TEQX000632		000632	N	1	0		

Report executed at: 9/18/2023 11:23:45 AM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

_		T	I	Taaaaaaa aa	I						T -		
2	03/30/2023	315503	TRANSAM	SANCROFT, ROMAINE	S526727942060	FL	06/06/1994	TX	6JT90APGAR	N	2	3	
	Vehicle \	/iolation:	393.95(a)	No/discharged/unsecured fire extinguisher									
	Vehicle \	Violation:	393.11	Truck-Tractor lower rear mud flaps retroreflective reflective material requirements for vehicles man 1997									
	Vehicle \	/iolation:	392.2	Wheel (Mud) Flaps missing or defective NON-OOS									
Violati	Violation Summary												
V	Violation # Description							# of Violation	ons	# of Out-of-s Violatio			
393.95((a)	No/discharge		1		0							
393.11		Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997										0	
392.2		Wheel (Mud) Flaps missing or defective										0	

The summary counts and rates only include violations that were attributable to SANCROFT, ROMAINE.

Report executed at: 9/18/2023 11:23:45 AM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.