

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
LAREDO		EDUARDO		L630216712960			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	07/11/2021	2901390	ABSOLUTE TOTAL SERVICES LLC	LAREDO, EDUARDO	L630216712960	FL	08/16/1971	PA	E927119215	N	3	0			

Report executed at: 10/2/2023 12:23:58 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	10/20/2022	3723784	GEORGE FREIGHT SOLUTIONS LLC	LAREDO, EDUARDO	L630216712960	FL	08/16/1971	OH	3274024657	N	1	3
Vehicle Violation: 393.95(a) No/discharged/unsecured fire extinguisher NON-OOS Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS												
3	07/20/2023	3723784	GEORGE FREIGHT SOLUTIONS LLC	LAREDO, EDUARDO	L630216712960	FL	08/16/1971	MN	00VM008150	N	3	1
Driver Violation: 392.2 Failure to obey traffic control device NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.95(a)	No/discharged/unsecured fire extinguisher								1	0		
393.47(e)	Clamp or Roto type brake out-of-adjustment								1	0		
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear								1	0		
392.2	Failure to obey traffic control device								1	0		

The summary counts and rates only include violations that were attributable to LAREDO, EDUARDO.

Report executed at: 10/2/2023 12:23:58 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>