

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
SOSA	AROLFO	A223001653831	FL										
ACOSTASOSA	AROLFO	A223001653831	FL										
ACOSTA	ACOSTASOSA	A223001653831	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		1	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		1		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	07/02/2022	3794233		ACOSTA SOSA, AROLFO	A223001653831	FL	10/23/1965	FL	FL2496447502	INTERSTAT E 95 (STATE ROAD 9)	0	0	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		5		Vehicle Inspections:		3		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		67%		Hazmat Out-of-service Rate:				0%	

Report executed at: 9/29/2023 2:02:35 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/28/2020	3195675	SAFEWAY LOGISTIC LLC	ACOSTA, AROLFO	A223001653831	FL	10/23/1965	TX	5TLA9DBD0B	N	4	1
Driver Violation: 392.2				Improper lane change			NON-OOS					
2	04/27/2021	3495035	IDD TRUCKING LLC	ACOSTA SOSA, AROLFO	A223001653831	FL	10/23/1965	FL	3493002046	N	3	1
Driver Violation: 392.2				Failure to obey traffic control device			NON-OOS					
3	06/01/2021	3495035	IDD TRUCKING LLC	ACOSTA, AROLFO	A223001653831	FL	10/23/1965	TX	61AB0VIPQ5	N	2	6
Vehicle Violation: 393.95(a)				No/discharged/unsecured fire extinguisher			NON-OOS					
Vehicle Violation: 393.78				Windshield wipers inoperative/defective			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 393.11				Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 385.13(d)				Failing to comply with an Unsatisfactory Out of Service Order			OOS					
4	08/24/2021	3643344	ENHANCED TRUCKING LLC	ACOSTA, AROLFO	A223001653831	FL	10/23/1965	UT	21TS000383	N	3	0
5	09/05/2021	3643344	ENHANCED TRUCKING LLC	AROLFO ANTONIO, ACOSTA SOSA	A223001653831	FL	10/23/1965	TN	TCTF000825	N	1	2
Driver Violation: 391.11(b)(2)				Driver cannot read or speak the English language sufficiently to respond to official inquiries.			NON-OOS					
Vehicle Violation: 392.9(a)				Failing to secure load			OOS					
6	05/20/2022	3794233	GLOBAL ACTIVATOR GROUP LLC	ACOSTA, AROLFO	A223001653831	FL	10/23/1965	TX	6B3C0XCGIV	N	2	6
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 393.78				Windshield wipers inoperative/defective			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperable head lamps			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperative turn signal			NON-OOS					

Report executed at: 9/29/2023 2:02:35 PM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
391.11(b)(2)	Driver cannot read or speak the English language sufficiently to respond to official inquiries.	1	0
392.9(a)	Failing to secure load	1	1
392.2	Failure to obey traffic control device	2	0
393.9(a)	Inoperable Required Lamp	7	0
393.78	Windshield wipers inoperative/defective	2	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997	1	0
385.13(d)	Failing to comply with an Unsatisfactory Out of Service Order	1	1

The summary counts and rates only include violations that were attributable to SOSA, AROLFO.

Report executed at: 9/29/2023 2:02:35 PM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.