

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																	
Last Name			First Name			License #			State								
VELEZ			EMILIO			867466741			NY								
Crash Activity																	
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0			
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0			
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries						
Inspection Activity (3 year history from MCMIS snapshot date)																	
Inspection Summary																	
Driver Summary				Vehicle Summary				Hazmat Summary									
Driver Inspections:				2		Vehicle Inspections:				1		Hazmat Inspections				0	
Driver Out-of-service Inspections:				0		Vehicle Out-of-service Inspections:				0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:				0%		Vehicle Out-of-service Rate:				0%		Hazmat Out-of-service Rate:				0%	
Inspection Details																	
Carrier Info				Driver Info				Inspection Info									
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol						
1	05/04/2021	2459419	POINT LOGISTICS LLC	VELEZ, EMILIO	867466741	NY	10/30/1972	OH	3248015617	N	1	2					
Vehicle Violation:		393.9(a)		Inoperable Required Lamp			NON-OOS										
Vehicle Violation:		392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.			NON-OOS										

Report executed at: 9/25/2023 9:50:42 AM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	10/04/2021	2459419	POINT LOGISTICS LLC	VELEZ, EMILIO	867466741	NY	10/30/1972	CT	3027000281	N	3	1
---	------------	---------	---------------------	---------------	-----------	----	------------	----	------------	---	---	---

Vehicle Violation:	392.2	Wheel (Mud) Flaps missing or defective	NON-OOS
--------------------	-------	--	---------

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.9(a)	Inoperable Required Lamp	1	0
392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.	2	0

The summary counts and rates only include violations that were attributable to VELEZ, EMILIO.

Report executed at: 9/25/2023 9:50:42 AM

MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>