PSP Detailed Report

Federal Motor Carrier Safety Administration

	Driver Information																				
Last	Name		F	First Name			Lic	License #							State						
ALEADELRISCO ALEA							A43	A434400644640							FL						
						Ci	rash	Activ	vity												
Cras	h Summary (Crashes liste	d represent a o	lriver's invol	vemer	nt in FMCSA-reportable	cras	hes,	without any	/ dete	rminat	ion as	to resp	onsibi	lity.)						
		#	t of Crashes: 1			# of Crashes with Fata	alities:	0			# of	Crashe	es with I	njuries:	rries: 0 # of			of Towa	Towaways: 1		
		# Not	preventable: 0			# of Fata	alities:	0					# of I	njuries:	0 # of Hazmat Releases				eases:	0	
Cras	Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																				
Date DOT # Carri			Carrier	Name		Driver Name		Drive	r Lic	State	Driver	er DOB Rpt St		Report Number		Location	ion # Fatalities		s # of Injuries		
1	09/28/2021	3632075			ISA	MAEL, ALEA DEL RISCO	Α4	34400	644640	FL	12/24	/1964	TN	TN0103103321		1-24	0		0		
	03/20/2021	0002010				,								110100	5100021	127			0		
				I	nspe	ction Activity (3 year	nist	ory t		is sn	apsno	ot date	e)								
Insp	ection Summ	-					<u></u>														
		Driver	Summary	_			/ehicle	e Sum	mary	_						azmat Sum	mary				
Drive	r Inspections:				5	Vehicle Inspections:						4 Ha	izmat In:	spection	IS					0	
Drive	r Out-of-servic	e Inspections:			2	Vehicle Out-of-service In	spection	ons:				4 Ha	izmat Oi	ut-of-ser	vice Insp	ections:			0		
Drive	r Out-of-servic	e Rate:			40%	Vehicle Out-of-service Rate:					10	00% Ha	% Hazmat Out-of-service Rate: 0							0%	
Insp	ection Detail	6																			
Carı	ier Info				Driver	r Info								Inspect	tion Info						
	Date	DOT #	Carrier	Name		Driver Name			Driver Lic		State	Driver DOB		Rpt St	Report Number		Hazmat Insp	Insp Le		# of Viol	
1	07/26/2021	3632075	LUBY INCOR	PORATION	ALEA [DEL RISCO, ISMAEL		A	43440064464	40	FL 12/24/1964		NM	9328L5R4S1		N	2		2		
			393.75(a)(3)			r audible air leak						OS									
	Vehicle	e Violation:	393.75(a)(3)	Tire-fla	at and/o	r audible air leak					C	OS									

Report executed at: 10/18/2023 1:08:13 PM

MCMIS snapshot date: 09/29/2023

2	09/15/2021	3632075	LUBY INCORPORAT	ION	ALEA DEL RISCO, ISMAEL	A434400644640	FL	12/24/1964	WA	W338000786	Ν	2	10	
	Driver Violation:		392.2	P.2 Failure to obey traffic control device			NON-C	OS						
Driver Violation:		392.16(a)	Failing to use seat belt while operating a CMV			NON-C	OS							
	Vehicle Violation:		393.78	Winds	shield wipers inoperative/defective		NON-C	OOS						
Vehicle Violation:		iolation:	393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997			NON-C	OOS						
	Vehicle Violation:		393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove			NON-C	OOS						
	Vehicle Vi	iolation:	393.75(a)(3))(3) Tire-flat and/or audible air leak				OOS						
	Vehicle Violation:		393.75(a)(3)	(3) Tire-flat and/or audible air leak				OOS						
	Driver Violation:		395.8(e)(1)	False report of drivers record of duty status				OOS						
	Driver Violation:		395.24(c)(2)(ii)	Driver failed to manually add the trailer number			NON-C	OOS						
	Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)				OOS						
3	09/28/2021	3632075	LUBY INCORPORAT	ION	RISCO, ALEA	A434400644640	FL	12/24/1964	TN	MDUH000972	Ν	2	5	
	Driver Violation:		395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)				OOS						
	Vehicle Violation:		393.100(b)	Leaking/spilling/blowing/falling cargo			C	OS						
	Vehicle Violation:		393.9(a)	Inoperable Required Lamp			OOS							
Vehicle Violation:		392.9(a)(2)	2.9(a)(2) Failing to secure vehicle equipment			C	OOS							
Vehicle Violation:		iolation:	392.2	Dimension Violation (Width / Height / Length)			NON-C	OOS						
4	08/24/2023	3979732	KJW FREIGHT LL	0	ALEA DEL RISCO, ISMAEL	A434400644640	FL	12/24/1964	CO	PF31202811	Ν	1	15	

Report executed at: 10/18/2023 1:08:13 PM MCMIS snapshot date: 09/29/2023

	Driver Vi	olation:	392.2	Miscellaneou	us Traffic Law Violation		NON-C	DOS						
Driver Violation: 395.		395.24(c)(2)(ii)	Driver failed to manually add the trailer number			NON-C	DOS							
Driver Violation:		olation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number				NON-OOS						
Driver Violat		olation:	395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD			NON-C	NON-OOS						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)				NON-OOS							
Vehicle Violation:		393.9(a)	Inoperative turn signal				SOS							
	Vehicle V	/iolation:	393.75(c)	Tire-other tre tread groove	ead depth less than 2/32 of inch meas	of inch measured in a major NON-C								
	Vehicle \	violation:	396.3(a)(1)	Brake - Leak	from air chamber		NON-C	DOS						
	Vehicle V	violation:	396.5(b)	Oil and/or gre	ease leak		NON-0	DOS						
	Vehicle V	violation:	396.3(a)(1)	Brake - Hole	in Spring Brake Housing		C	DOS						
	Vehicle V	violation:	396.3(a)(1)	Brake - Hole	in Spring Brake Housing		C	DOS						
	Vehicle V	violation:	396.3(a)(1)	Brake - Hole in Spring Brake Housing			C	DOS						
	Vehicle V	violation:	396.3(a)(1)	Brake - Hole in Spring Brake Housing			OOS							
	Vehicle Violation: 393.45(b)(2)		Brake Hose or Tubing Chafing and/or Kinking Under Vehicle NON-OOS											
	Vehicle Violation:		396.3(a)(1)		JT OF SERVICE: The number of defe reater than 20 percent of the service I mbination		C	DOS						
5	09/18/2023	3979732	KJW FREIGHT LL	C ALEA,	, ISMAEL	A434400644640	FL	12/24/1964	MS	6618092063	Ν		3	0
	on Summary				Description					# of Violat	ions	# of	Out-of-se Violatior	
													VIOIALIOI	15
393.75(a	a)(3)	Tire-flat and	/or audible air leak								4			4
392.2		Failure to obey traffic control device									3			0
392.16(a	a)	Failing to us	e seat belt while operating	g a CMV							1			0
393.78	393.78		Windshield wipers inoperative/defective											0
393.11		Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997									1			0
393.75(c) T		Tire-other tread depth less than 2/32 of inch measured in a major tread groove									2			0
395.8(e)(1) False report of drivers record of duty status											1			1
395.24(c)(2)(ii) Driver failed to manually add the trailer number											2			0
395.8		Record of Duty Status violation (general/form and manner)									2			0
395.24(c)(2)(iii)	Driver failed	to manually add shipping	document num	nber						1			0

Report executed at: 10/18/2023 1:08:13 PM

MCMIS snapshot date: 09/29/2023

395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	1	0
393.9(a)	Inoperative turn signal	2	1
396.3(a)(1)	Brake - Leak from air chamber	6	5
396.5(b)	Oil and/or grease leak	1	0
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle	1	0
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)	1	1
393.100(b)	Leaking/spilling/blowing/falling cargo	1	1
392.9(a)(2)	Failing to secure vehicle equipment	1	1

The summary counts and rates only include violations that were attributable to ALEADELRISCO, ALEA.

Report executed at: 10/18/2023 1:08:13 PM MCMIS snapshot date: 09/29/2023