

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #				State							
SANCHEZ		NESTOR		S522630663310				FL							
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	02/21/2021	2635313	CONTINENTAL FREIGHT INC	SANCHEZ, NESTOR	S522630663310	FL	09/11/1966	NJ	SPBOI00816	N	3	0			

Report executed at: 10/27/2023 9:30:54 AM

MCMIS snapshot date: 09/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	10/15/2021	2635313	CONTINENTAL FREIGHT INC	SANCHEZ, NESTOR	S522630663310	FL	09/11/1966	UT	22GP000009	N	3	1
Driver Violation:			392.2	State/Local Laws - Excessive weight - More than 5000 lbs over on an axle/axle groups.			NON-OOS					
3	05/25/2022	2443366	RNDY TRANSPORT INC	SANCHEZ, NESTOR	S522630663310	FL	09/11/1966	CO	PF04405676	N	1	7
Vehicle Violation:			393.45(d)	Brake connections with leaks or constrictions			OOS					
Vehicle Violation:			390.21T(b)	Carrier name and/or USDOT Number not displayed as required			NON-OOS					
Vehicle Violation:			393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit			NON-OOS					
Vehicle Violation:			393.11	No or defective lighting devices or reflective material as required			NON-OOS					
Vehicle Violation:			393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle			NON-OOS					
Vehicle Violation:			393.48(a)	Inoperative/defective brakes			OOS					
Vehicle Violation:			393.67(c)(7)(v)	Fuel tank fill pipe cap missing			NON-OOS					
4	01/22/2023	2089174	AREL TRUCKING INC	SANCHEZ, NESTOR	S522630663310	FL	09/11/1966	OK	PE11183245	N	1	2
Vehicle Violation:			393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS					
Vehicle Violation:			393.9(a)	Inoperable tail lamp			NON-OOS					
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		State/Local Laws - Excessive weight - More than 5000 lbs over on an axle/axle groups.							1		0	
393.45(d)		Brake connections with leaks or constrictions							1		1	
390.21T(b)		Carrier name and/or USDOT Number not displayed as required							1		0	
393.45(b)(2)		Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit							2		0	
393.11		No or defective lighting devices or reflective material as required							1		0	
393.48(a)		Inoperative/defective brakes							1		1	
393.67(c)(7)(v)		Fuel tank fill pipe cap missing							1		0	
393.95(a)		No/discharged/unsecured fire extinguisher							1		0	
393.9(a)		Inoperable tail lamp							1		0	

The summary counts and rates only include violations that were attributable to SANCHEZ, NESTOR.

Report executed at: 10/27/2023 9:30:54 AM

MCMIS snapshot date: 09/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>