



WITH YOU
TO HAUL
& BACK.

5211 N GRANITE LN.
SIOUX FALLS, SD
57107
605/336-6198

REMIT TO:
MICHELIN NORTH AMERI
12398 COLLECTIONS CE
CHICAGO, IL 60693-039

DR #: DR3171971

PAGE: 1

CUSTOMER: ENGLAND CARRIER SERVICES (STK/
4701 W 2100 S
3106468
SALT LAKE CITY, UT
84120-0000

#824

DR NUMBER: DR3171971

VEHICLE: 2023 HYUNDAI
LICENSE: 450405T TN
DUE: 09/10/24

WRK ORD DATE: 08/16/24

PRODUCT	QUANTITY
MOP:EFS/CHANGED TO NATIONAL ACCOUNT	
LOCATION:IN SHOP	
REF# 95096 AUTH BY:SAM CB#801-656-4699	
DRIVER NAME: JOSE CB#201-640-7590	
TRUCK# 824 TRAILER# 8244742 T.O.C:	

REPAIR REQUEST:COMAPANY CALLED FOR CHECK/ADVISE RRO/LRI TRL TIRES	

**TECH FOUND RRO HAD 2 HOLES WITHIN 3IN OF EACHOTHER SO NEEDS REPLACING, LRI	
HAD PREVIOUSLY BEEN PATCHED AND WAS LEAKING AT THAT SAME HOLE PATCH- NEEDS TO	
BE REPLACED ALSO***	

MNA MOUNT/DISMOUNT S1125	2
S1125	
295/75R22.5G X LINE ENRGY T2 TLR	2
41669	
NEW DOT # IHAJF107X3223 OLD DOT #IFABTYJAW1424/IFABTYAW1524	
POS:LRO/LRI	
VALVE STEM	2
S0631	
VALVE CORE	2
S0197	
VALVE CAP	2
S0197	
OFF BRAND: MICH CAUSE OF FAIL: HOLE/LEAK 11/9	
/32NDS	
MNA MOUNT/DISMOUNT S1125	1
S1125	

CUSTOMER CALLED BACK AFTER TIRES INSTALLED AND WANTED ANOTHER ROTATE FOR NEW	
TIRES TO BE SIDE BY SIDE/ DRIVER TOOK OLD TIRES WITH HIM*****	
NEW MICH TIRES MOUNTED ON LRI/LRO ON TRL	

Thank You For Your Business!
Boss Truck Shops - With You to Haul and Back



WITH YOU
TO HAUL
& BACK.

PAGE: 2

CUSTOMER: ENGLAND CARRIER SERVICES (STK/

PRODUCT

QUANTITY

THIS ACCOUNT IS "ENGLAND CARRIERS", NOT "C.R. ENGLAND".

1. EMAIL WORK ORDER TO THE LOCATION THAT REQUESTED TIRES / SERVICES

2. PO WILL BE PROVIDED WITHIN 24-48 HOURS.

NOTE: PO WILL BE AVAILABLE THROUGH SHOP CONNECT (IF LOVE'S) AND
ESHOP (IF TA).

PO NUMBER

VEHICLE #

RECEIVED BY NAME

TELEPHONE

8008487810

Customer Signature : _____

Printed Name: _____