



FMCSA ANNUAL INSPECTION FORM

HYUNDAI TRANSLEAD

Plant: Blvd. Hyundai No. 41, Col. Ampliación Constitución,
Playas de Rosarito, Baja California, MX. CP 22707
Corporate Office: 8880 Rio San Diego Drive, Ste # 600
San Diego, CA 92108

Inspection Facility: HT Rosarito Plant	Unit Number: PTL22A2130	Hubodometer (if applicable): OK
City and State: Rosarito, Baja California, MX.	Customer: PREMIER	S.A.P. Number: 30070117
Inspector Name: Humberto Galvan	VIN Number: 3H3Y53761K51182S	License Plate Number: 490707
Inspection Date: 06/07/23 <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Repair Date: N/A	Year / Model: 2021 / FUS30152-ATS

OK	NEEDS REPAIR	ITEMS INSPECTED	OK	NEEDS REPAIR	ITEMS INSPECTED
		BRAKE SYSTEM			SAFE LOADING
/		Service Brakes			Part(s) of vehicle or condition of loading such as spare tire or any part of the load or dunnage can fall onto the roadway
/		Parking Brake System	N		Protection against shifting cargo
/		Brake Drums or Rotors		A	STEERING MECHANISM
/		Brake Hose			For units with Steerable Rear Axle.
/		Brake Tubing			SUSPENSION
/		Audible Air Leaks	N	A	Any U Bolt(s), spring hanger(s) or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from it's normal position
		COUPLING DEVICES			Spring assembly
/		Fifth Wheels / Upper Coupler			Torque, radius or tracking component
N		Pintle Hooks			FRAME
		Drawbar / Towbar Eye			Frame members
		Drawbar / Towbar Tongue	/		Tire and Wheel Clearance
		Safety Devices	/		Adjustable Axle Assemblies (Sliding Sub-Frames).
	A	Saddle-Mounts	/		TIRES
		EXHAUST SYSTEM / REFRIGERATED UNITS			WHEELS AND RIMS
N		No part of the exhaust system of any motor vehicle shall be located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle	N	A	Lock or Side Ring
		FUEL SYSTEM / REFRIGERATED UNITS	/		Wheels and Rims
N		Visible leak	/		Fasteners
		Fuel tank filler cap missing	/		Welds
	A	Fuel tank securely attached	/		UNIT NUMBERS DISPLAYED
		LIGHTING DEVICES	/		SPLASH GUARDS
/		All lighting devices and reflectors required by Section 393 shall be operable.	/		Driver Side
			/		Passenger Side

I have inspected the vehicle described above and certify that all entries are true and correct. I certify that this inspection meets the requirements of 49 CFR Part 396.17 and is in accordance with Appendix G to Subchapter B, Minimum Periodic Inspection Standards, and the vehicle has passed / failed as indicated above.

INSPECTOR'S NAME (Please Print): Humberto Galvan

INSPECTOR'S SIGNATURE: Humberto Galvan