ANNUAL VEHICLE INSPECTION REPORT

| VEHICLE HISTORY RECORD | | | | | |
|------------------------|-------------------|--|--|--|--|
| REPORT NUMBER | FLEET UNIT NUMBER | | | | |
| | | | | | |
| DATE | | | | | |

| MOTOR CARRIER OPERATOR ZIGI FREIGHT INC dba ROYAL3 INC | INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOVACEVIC | | | | |
|--|---|--|--|--|--|
| 6850 W. 63rd STREET | THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES | | | | |
| CHICAGO, IL 60638 | VEHICLE INDETIFICATION (✓ AND COMPLETE) ☐ LIC.PLATE NO. ☑ VIN ☐ OTHER | | | | |
| VEHICLE TYPE ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER) | INSPECTION AGENCY/LOCATION (OPTIONAL) | | | | |

| OTHER TRACTOR TRUCK BUS INSPECTION AGENCY/LOCATION (OPTIONAL) | | | | | | | | | | | |
|---|-----------------|------------------|--|----|-----------------|------------------|-------------------------------------|----|-----------------|------------------|--|
| VEHICLE COMPONENTS INSPECTED | | | | | | | | | | | |
| ОК | NEEDS REPAIR | REPAIRED DATE | ITEM | ОК | NEEDS REPAIR | REPAIRED DATE | ITEM | ОК | NEEDS REPAIR | REPAIRED DATE | ITEM |
| | | | 1. BRAKE SYSTEM | | | | 6. SAFE LOADING | | | | 12. WINDSHEILD GLAZING |
| V | | | a. Service Brakes | | | | a. Vehicle parts, load, | | | | No cracks, discoloration, |
| | | | b. Parking Brake System | | | | dunnage, spare tire, etc., secured. | | | N/A | obstacles, etc. (see 393.60 for |
| | | | c. Brake Drums or Rotors | | | | | | | | exceptions). |
| | | | d. Brake Hose | | | | b. Front End Structure | | | | 13. WINDSHEILD WIPERS |
| | | | e. Brake Tubbing | | | N/A | c. Intermodal Container | | 0 | N/A | No missing, Damaged, or |
| | | N/A | f. Low Pressure Warning | | | 14/ 🖰 | Securement Devices | | | 14/ 🔼 | inoperable wipers. |
| | u | IN/ A | Device | | | | 7. STEERING MECHANISM | | | | 14. MOTORCOACH SEATS |
| | | N/A | g. Tractor Protection Valve | | | N/A | a. Steering Wheel Free Play | | | N/A | Seats securely fastened to the vehicle |
| | | N/A | h. Air Compressor | | | N/A | b. Steering Column | | | N/A | structure. |
| | | N/A | i. Electric Brakes | | | NI/A | c. Front Axle Beam/All | | | | 15. REAR IMPACT GUARD |
| | | N/A | j. Hydraulic Brakes | | | N/A | Other Steering Components | | | | |
| | | N/A | k. Vakum Systems | | | N/A | d. Steering Gear Box | | | | In place, securely attached, proper size, proper placement (see 393.86). |
| | | | I. Antilock Brake System | | | N/A | e. Pitman Arm | | | | proper placement (see sssies). |
| | | | m. Automatic Brake Adjusters | | | N/A | f. Power Steering | | | | 16. OTHER |
| | | | 2. COUPLING DEVICES | | | N/A | g. Ball and Socket Joints | | | | List any other condition(s) |
| | | N/A | a. Fifth Wheels | | | N/A | h. Tie Rods and Drag Links | | | | which may prevent safe operation of this vehicle. |
| | | N/A | b. Pintle Hooks | | | N/A | i. Nuts | | | | · |
| | | N/A | c. Drawbar/Towbar Eye | | | N/A | j. Streering System | | | | |
| | | N/A | d. Drawbar/Towbar Tongue | | | | 8. SUSPENSION | | | | |
| | | N/A | e. Safety Devices | | | | a. Axle Positioning Parts | | | | |
| | | N/A | f. Saddle-Mounts | | | | b. Spring Assembly | | | | |
| | | | 3. EXHAUST SYSTEM | | | | c. Torque, Radius or Tracking | | | | |
| | | | a. No leaks forward of/ | | | | Components | | | | |
| | | N/A | directly below the driver/ sleeper compartment. | | | | 9. FRAME | | | | |
| | | | · | | | | a. Frame Members | | | | // LW99ED /\ |
| | | | b. Bus: No leaking/ | | | | b. Tire and Wheel Clearance | | | | |
| | | N/A | discharging in violation of standard. | | | | c. Adjustable Axle | | | | |
| | | | | | | | Assemblies (Sliding Subframes) | | | | |
| | | | c. Unlikely to burn, char, | | | | | | | | |
| | | N/A | or damage the electrical wiring, fuel supply, or any | | | | 10. TIRES | | | | |
| | | | combustible part of vehicle. | | | N/A | a. Steer-Axle Tires | | | | |
| | | | 4. FUEL SYSTEM | | | | b. All Other Tires | | | | |
| | | N/A | a. No visible Leak. | | | N/A | c. Speed-Restricted Tires | | | | |
| | | N/A | b. Fuel tank filler cap | | | | 11. WHEELS AND RIMS | | | | |
| | | N/A | c. Fuel tank securely attached. | | | | a. Lock or Side Ring | | | | |
| | | | 5. LIGHTING DEVICES | | | | b. Wheels and Rims | | | | |
| | | | a. All required light/reflectors | | | | c. Fasteners | | | | |
| | J | | operable. | | | | d. Welds | | | | |
| INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: V OK, NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE | | | | | | | | | | | |

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.