| By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17. Inspection conducted by: Inspection condu | 00 hours of 2 | e Ro Middle | 13 Villanty 16 RO Front 13 | TIRES (in 32nds)     Brand     Brakes       Position     TD     Brand     PSL       Axle     Axle | Flatbed Winches – Lubricate and Cycle | Suspension / U-Bolts / Springs | Shack Adjusters / S-cams / Brake adjustment - Lubricate & adjust Repaired LOOT Inspected | Brakes – ADB / Rotors, Calipers, Pistons, Chambers, Pads Repaired Linterior – Resec | Brakes - Drums / Linings /Air Chambers Repaired Interior Trailer - | Air Tank and Mounting Brackets Repaired Arrhinges, Roll | Syspension Hangers                                      | Arr Lines - Check for damage / wear / chaffing | ABS System - Actuate Repaired Rear Impact Guard | The prime value (Air Ride Only) - Testoperation and check for Leaks Repaired Line Mudflaps, Brac | Air Brake System - Test for Leaks                    | FateTank and Fuel System (Reefer) | Landing Gear Legs /Gear Box and Bracing - Lubricate & Cycle Repaired Lygnuts - Torq | Repaired Lifes - free of in            |  |
|--|---------------|-------------|----------------------------|---|---------------------------------------|--------------------------------|--|---|--|---|---|--|---|--|--|-----------------------------------|---|--|--|
| in compliance with all of the requirements of 49 C.F te: $04/23/25$  | Ste<br>216    |             | R Front TX Enoine Hrs:     | (Drum in 8ths / ADB in mm)<br>Position Depth  |                                       | nia BIT Inspected & Passed     | DOT Inspected – Sticker Applied  | - Resecure Plywood as Needed  | Trailer – Floor, Roof, and Side Walls                              | Alt Hinges, Rollers, Locks - Lubricate                  | Door Hold Backs and Pull Handles - Present & Functional | <ul> <li>Proper Operation</li> </ul>           | buard   | Mudflaps, Brackets, and Rubber Dock Bumpers  | Conspicuity Tape-Side Panels, Rear Doors, Headboards | Flow-Thru Valve Stem Caps         | Lugnuts – Torque to 450-500 ft/lbs – Set wrench to 500 ft/lbs                       | - free of impermissible damage or wear | Superior of States and State |

Registration, Valid License Plate and sticker

Way Electrical Plug

Prad Hands & Rubber Grommets

Equipment ID OTRT H10506

**VIV** 

5V8VC5323ST502233

2025 Year

VANGUARD Manufacturer

ME 5308325 **Primary Plate** 

Check Mark = OK

XTRA Lease DOT / BIT Inspection and PM Worksheet

X = Needs Further Attention , R = Repaired

Repaired Repaired

Sub-Frame – Slide Rails and Crossmembers

N/A = Not Applicable

Aerodynamic Side Skirts

Slider Mechanism & Locking Pins - Lubricate, Release, Re-

Repaired Repaired Repaired

Repaired

engage

Company Name: XTRA Lease LLC

21

Print Name:

(Inspector signature)