

Equipment ID
OTRT H11606

VIN
5V8VC5320ST502657

Year
2025

Manufacturer
VANGLARD

Primary Plate
ME 5309343

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK

X = Needs Further Attention

R = Repaired

N/A = Not Applicable

☒	Glad Hands & Rubber Grommets	☐	Repaired	☒	Sub-Frame - Slide Rails and Crossmembers	☐	Repaired
☒	7-Way Electrical Plug	☐	Repaired	☒	Aerodynamic Side Skirts	☐	Repaired
☒	Registration, Valid License Plate and sticker	☐	Repaired	☐	Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage	☐	Repaired
☒	Lights, Wiring and Splice Conditions	☐	Repaired	☒	Proper Lubricant Level in each Wheel End - Fill if necessary	☐	Repaired
☒	Exterior Trailer - Body Condition and Coupling Device	☐	Repaired	☒	Wheels - Check for Cracks / Tire Matching	☐	Repaired
☒	Corner Locking Devices	☐	Repaired	☒	Tires - free of impermissible damage or wear	☐	Repaired
☒	Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	☐	Repaired	☒	Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	☐	Repaired
☒	Fuel Tank and Fuel System (Reefer)	☐	Repaired	☒	Metal Flow-Thru Valve Stem Caps	☐	Repaired
☒	Air Brake System - Test for Leaks	☐	Repaired	☒	Conspicuity Tape-Side Panels, Rear Doors, Headboards	☐	Repaired
☒	Dump Valve (Air Ride Only) - Test operation and check for Leaks	☐	Repaired	☒	Mudflaps, Brackets, and Rubber Dock Bumpers	☐	Repaired
☒	ABS System - Actuate	☐	Repaired	☒	Rear Impact Guard	☐	Repaired
☒	Air Lines - Check for damage / wear / chaffing	☐	Repaired	☒	Doors - Proper Operation	☐	Repaired
☒	Suspension Hangers	☐	Repaired	☒	Door Hold Backs and Pull Handles - Present & Functional	☐	Repaired
☒	Air Tank and Mounting Brackets	☐	Repaired	☒	All Hinges, Rollers, Locks - Lubricate	☐	Repaired
☒	Brakes - Drums / Linings / Air Chambers	☐	Repaired	☒	Interior Trailer - Floor, Roof, and Side Walls	☐	Repaired
☒	Brakes - ADB / Rotors, Callipers, Pistons, Chambers, Pads	☐	Repaired	☒	Interior - Resecure Plywood as Needed	☐	Repaired
☒	Slack Adjusters / S-Cams / Brake adjustment - Lubricate & adjust	☐	Repaired	☒	DOT Inspected - Sticker Applied	☐	Repaired
☒	Suspension / U-Bolts / Springs	☐	Repaired	☒	California BIT Inspected & Passed	☐	Repaired
☒	Flatbed Winches - Lubricate and Cycle	☐	Repaired	☐	NOTES:	☐	

TIRES (in 32nds)					
Axle	Position	TD	Brand	PSI	Position
1	LO Front	12	Yokohama	100	RI Front
	LI Front	12	Yokohama	100	RO Middle
	LO Middle	12	Yokohama	100	RI Middle
2	LO Middle	12	Yokohama	100	RO Rear
	LI Middle	12	Yokohama	100	RI Rear
	LO Rear	12	Yokohama	100	RI Rear
3	LO Rear	12	Yokohama	100	RI Rear
	LI Rear	12	Yokohama	100	RI Rear
	LO Rear	12	Yokohama	100	RI Rear

Brakes (Drum in 8ths / ADB in mm)			
Axle	Position	Depth	Hubo.
1	L Front	7/8	2996
	R Front	7/8	
	L Middle	7/8	
2	L Middle	7/8	Fuel 8ths:
	R Middle	7/8	
	L Rear	7/8	
3	L Rear	7/8	
	R Rear	7/8	
	L Rear	7/8	

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: Mark Lee
(Inspector signature)

Company Name: Cox Automotive Mobility Fleet Services

Print Name: Mark Lee

Inspection Date: 4-8-25

