

Equipment ID	VIN	Year	Manufacturer	Primary Plate
OTRT H11575	5V8VC5320ST502626	2025	VANGUARD	ME 5309312

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

<input checked="" type="checkbox"/> Glad Hands & Rubber Grommets	Repaired	<input type="checkbox"/>	Sub-Frame - Slide Rails and Crossmembers	Repaired
<input checked="" type="checkbox"/> 7-Way Electrical Plug	Repaired	<input type="checkbox"/>	Aerodynamic Side Skirts	Repaired
<input checked="" type="checkbox"/> Registration, Valid License Plate and sticker	Repaired	<input type="checkbox"/>	Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage	Repaired
<input checked="" type="checkbox"/> Lights, Wiring and Splice Conditions	Repaired	<input type="checkbox"/>	Proper Lubricant Level in each Wheel End - Fill if necessary	Repaired
<input checked="" type="checkbox"/> Exterior Trailer - Body Condition and Coupling Device	Repaired	<input type="checkbox"/>	Wheels - Check for Cracks / Tire Matching	Repaired
<input checked="" type="checkbox"/> Corner Locking Devices	Repaired	<input type="checkbox"/>	Tires - free of impermissible damage or wear	Repaired
<input checked="" type="checkbox"/> Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	Repaired	<input type="checkbox"/>	Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	Repaired
<input checked="" type="checkbox"/> Fuel Tank and Fuel System (Reefer)	Repaired	<input type="checkbox"/>	Metal Flow-Thru Valve Stem Caps	Repaired
<input checked="" type="checkbox"/> Air Brake System - Test for Leaks	Repaired	<input type="checkbox"/>	Conspicuity Tape-Side Panels, Rear Doors, Headboards	Repaired
<input checked="" type="checkbox"/> Dump Valve (Air Ride Only) - Test operation and check for Leaks	Repaired	<input type="checkbox"/>	Mudflaps, Brackets, and Rubber Dock Bumpers	Repaired
<input checked="" type="checkbox"/> ABS System - Actuate	Repaired	<input type="checkbox"/>	Rear Impact Guard	Repaired
<input checked="" type="checkbox"/> Air Lines - Check for damage / wear / chaffing	Repaired	<input type="checkbox"/>	Doors - Proper Operation	Repaired
<input checked="" type="checkbox"/> Suspension Hangers	Repaired	<input type="checkbox"/>	Door Hold Backs and Pull Handles - Present & Functional	Repaired
<input checked="" type="checkbox"/> Air Tank and Mounting Brackets	Repaired	<input type="checkbox"/>	All Hinges, Rollers, Locks - Lubricate	Repaired
<input checked="" type="checkbox"/> Brakes - Drums / Linings / Air Chambers	Repaired	<input type="checkbox"/>	Interior Trailer - Floor, Roof, and Side Walls	Repaired
<input checked="" type="checkbox"/> Brakes - ADB / Rotors, Calipers, Pistons, Chambers, Pads	Repaired	<input type="checkbox"/>	Interior - Resecure Plywood as Needed	Repaired
<input checked="" type="checkbox"/> Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Repaired	<input type="checkbox"/>	DOT Inspected - Sticker Applied	Repaired
<input checked="" type="checkbox"/> Suspension / U-Bolts / Springs	Repaired	<input type="checkbox"/>	California BIT Inspected & Passed	Repaired
<input checked="" type="checkbox"/> Flatbed Winches - Lubricate and Cycle	Repaired	<input type="checkbox"/>	NOTES:	Repaired

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	12	Valvoline	100	RO Front	12	Valvoline	100
	LI Front	12	Valvoline	100	RI Front	12	Valvoline	100
2	LO Middle	N/A	N/A	N/A	RO Middle	N/A	N/A	N/A
	LI Middle	12	Valvoline	100	RI Middle	12	Valvoline	100
3	LO Rear	12	Valvoline	100	RO Rear	12	Valvoline	100
	LI Rear	12	Valvoline	100	RI Rear	12	Valvoline	100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	13/16"
	R Front	13/16"
2	L Middle	N/A
	R Middle	13/16"
3	L Rear	13/16"
	R Rear	13/16"

Hubo: 3100

Engine Hrs: 2

Prot. Time: 2

Fuel 8ths: 0

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: H. Helms (Inspector signature)

Inspection Date: 04/25/2025

Print Name: H. Helms

Company Name: Fleet Mobile Maintenance Inc