

Equipment ID	VIN	Year	Manufacturer	Primary Plate
OTRT H10473	5V8VC532XST502200	2025	VANGUARD	ME 5308292

XTRA Lease DOT / BIT Inspection and PM Worksheet
Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

<input checked="" type="checkbox"/> Glad Hands & Rubber Grommets	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> 7-Way Electrical Plug	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Registration, Valid License Plate and sticker	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Lights, Wiring and Splice Conditions	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Exterior Trailer - Body Condition and Coupling Device	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Corner Locking Devices	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Fuel Tank and Fuel System (Reefer)	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Air Brake System - Test for Leaks	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Dump Valve (Air Ride Only) - Test operation and check for Leaks	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> ABS System - Actuate	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Air Lines - Check for damage / wear / chaffing	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Suspension Hangers	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Air Tank and Mounting Brackets	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Brakes - Drums / Linings / Air Chambers	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Brakes - ADB / Rotors, Calipers, Pistons, Chambers, Pads	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Suspension / U-Bolts / Springs	Repaired	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/> Flatbed Winches - Lubricate and Cycle	Repaired	<input type="checkbox"/>	Repaired

NOTES:

TIRES (in 32nds)								
Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	12	100	100	RO Front	12	100	100
	LI Front	12	100	100	RI Front	12	100	100
2	LO Middle	N/A	N/A	N/A	RO Middle	N/A	N/A	N/A
	LI Middle	N/A	N/A	N/A	RI Middle	N/A	N/A	N/A
3	LO Rear	12	100	100	RO Rear	12	100	100
	LI Rear	12	100	100	RI Rear	12	100	100

Brakes (Drum in 8ths / ADB in mm)			
Axle	Position	Depth	Hubo:
1	L Front	13/16"	2770
	R Front	13/16"	N/A
2	L Middle	N/A	N/A
	R Middle	N/A	N/A
3	L Rear	7/8"	N/A
	R Rear	13/16"	N/A

Engine Hrs: N/A
Prot. Time: N/A
Fuel 8ths: N/A

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: H. H. Holmes (Inspector signature)

Inspection Date: 04/30/2025

Print Name: H. H. Holmes

Company Name: Fleet Mobile Maintenance Inc