

Equipment ID OTRT H11579	VIN 5V8VC5322ST502630	Year 2025	Manufacturer VANGUARD	Primary Plate ME 5309316
-----------------------------	--------------------------	--------------	--------------------------	-----------------------------

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

<input checked="" type="checkbox"/> Glad Hands & Rubber Grommets	<input type="checkbox"/> Sub-Frame - Slide Rails and Crossmembers	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> 7-Way Electrical Plug	<input checked="" type="checkbox"/> Aerodynamic Side Skirts	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Registration, Valid License Plate and sticker	<input checked="" type="checkbox"/> Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Lights, Wiring and Splice Conditions	<input checked="" type="checkbox"/> Proper Lubricant Level in each Wheel End - Fill if necessary	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Exterior Trailer - Body Condition and Coupling Device	<input checked="" type="checkbox"/> Wheels - Check for Cracks / Tire Matching	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Corner Locking Devices	<input checked="" type="checkbox"/> Tires - free of impermissible damage or wear	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	<input checked="" type="checkbox"/> Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Fuel Tank and Fuel System (Reefer)	<input checked="" type="checkbox"/> Metal Flow-Thru Valve Stem Caps	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Air Brake System - Test for Leaks	<input checked="" type="checkbox"/> Conspicuity Tape-Side Panels, Rear Doors, Headboards	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Dump Valve (Air Ride Only) - Test operation and check for Leaks	<input checked="" type="checkbox"/> Mudflaps, Brackets, and Rubber Dock Bumpers	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> ABS System - Actuate	<input checked="" type="checkbox"/> Rear Impact Guard	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Air Lines - Check for damage / wear / chaffing	<input checked="" type="checkbox"/> Doors - Proper Operation	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Suspension Hangers	<input checked="" type="checkbox"/> Door Hold Backs and Pull Handles - Present & Functional	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Air Tank and Mounting Brackets	<input checked="" type="checkbox"/> All Hinges, Rollers, Locks - Lubricate	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Brakes - Drums / Linings / Air Chambers	<input checked="" type="checkbox"/> Interior Trailer - Floor, Roof, and Side Walls	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Brakes - ADB / Rotors, Calipers, Pistons, Chambers, Pads	<input checked="" type="checkbox"/> Interior - Resecure Plywood as Needed	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	<input checked="" type="checkbox"/> DOT Inspected - Sticker Applied	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Suspension / U-Bolts / Springs	<input checked="" type="checkbox"/> California BIT Inspected & Passed	<input type="checkbox"/> Repaired
<input checked="" type="checkbox"/> Flatbed Winches - Lubricate and Cycle	NOTES:	<input type="checkbox"/> Repaired

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	12	Goodyear	100	RO Front	12	Goodyear	100
	LI Front	12	Goodyear	100	RI Front	12	Goodyear	100
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	12	Goodyear	100	RO Rear	12	Goodyear	100
	LI Rear	12	Goodyear	100	RI Rear	12	Goodyear	100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	1/8
	R Front	1/8
2	L Middle	
	R Middle	
3	L Rear	1/8
	R Rear	7/8

Hubo: 3612

Engine Hrs: _____

Prot. Time: _____

Fuel 8ths: _____

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: Kevin Parker
(Inspector signature)

Inspection Date: 4-30-25

Print Name: MAE air newlin

Company Name: Cox Automotive Mobility Fleet Services