OTI	Equipment ID OTRT H10508	VIN	VIN 5V8VC5327ST502235	02235	Year 2025		Manu VANG	Manufacturer VANGUARD		Primary Plate ME 5308327
			C	XTRA Lease Check Mark = OK		DOT / BIT Inspectic X = Needs Further Attention	ň	and PM Worksheet	rksheet N/A = Not Applicable	ble
2	Glad Hands & Rubber Grommets	bber Grommets				Repaired	Sub-F	Sub-Frame – Slide Rails and Crossmembers	ails and Crossr	lembers
2	7-Way Electrical Plug	Bnle				Repaired	Aerody	Aerodynamic Side Skirts	rts	
Ç	Registration, Valid License Plate and sticker	i License Plate	and sticker			Repaired	Slider	Mechanism & L	ocking Pins - L	Slider Mechanism & Locking Pins - Lubricate, Release, Re-
Q	Lights, Wiring and Splice Conditions	Splice Conditi	ons			Repaired		e r Lubricant Leve	l in each Whee	Proper Lubricant Level in each Wheel End - Fill if necessary
2	Exterior Trailer - Body Condition and Coupling Device	Body Condition	and Couplin	ng Device		Repaired	Wheels -		Check for Cracks / Tire Matching	shing
<u>ار</u>	Corner Locking Devices	evices				Repaired	Tires -	Tires - free of impermissible damage or wear	issible damage	or wear
2	Landing Gear Legs /Gear Box and Bracing - Lubricate & Cycle	s /Gear Box an	d Bracing - L	ubricate & Cycl	Ø	Repaired	Lugnuts -	ts - Torque to 4	450-500 ft/lbs	Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs
Ě	Fuel Tank and Fuel System (Reefer)	el System (Ree	fer)			Repaired	Metal	Metal Flow-Thru Valve Stem Caps	e Stem Caps	
K	Air Brake System - Test for Leaks	- Test for Leaks				Repaired	Consp	icuity Tape-Sic	le Panels, Rea	Conspicuity Tape-Side Panels, Rear Doors, Headboards
2	Dump Valve (Air Ride Only) - Testoperation and check for Leaks	Ride Only) - Tes	stoperation a	and check for L	eaks	Repaired	Mudflaps,	-	Brackets, and Rubber Dock Bumpers	k Bumpers
R	ABS System - Actuate	late				Repaired	Rear	Rear Impact Guard		
Ĺ	Air Lines - Check for damage / wear / chaffing	for damage / w	ear / chaffin	Ð		Repaired	Doors	Doors – Proper Operation	ation	
	Suspension Hangers	ers				Repaired	Door H	fold Backs and	Pull Handles -	Door Hold Backs and Pull Handles - Present & Functional
É	Air Tank and Mounting Brackets	nting Brackets				Repaired	All Hin	All Hinges, Rollers, Locks - Lubricate	ocks – Lubricat	
6	Brakes - Drums / Linings /Air Chambers	Linings /Air Cha	ambers			Repaired	Interior T	r Trailer – Floor	railer – Floor, Roof, and Side Walls	e Walls
É	Brakes – ADB / Rotors, Calipers, Pistons, Chambers, Pads,	otors, Calipers	, Pistons, C	hambers, Pads		Repaired	Mul Interior -		Resecure Plywood as Needed	led
2	Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	S-cams / Brake	e adjustmen	t – Lubricate &	adjust	Repaired		DOT Inspected – Sticker Applied	ker Applied	
	Suspension / U-Bolts / Springs	olts / Springs				Repaired	MCalifornia		BIT Inspected & Passed	
MARF	Flatbed Winches – Lubricate and Cycle	 Lubricate and 	d Cycle			Repaired	NOTES:			
			TIRES	š (in 32nds)				Brakes (Drun	(Drum in 8ths / ADB in mm)	mm)
Axle	Position	TD Brand			TD	Brand	PSI		Position Depth	
7	LO Front	12 YOLOHANA	And was	TI	12	YOUOHAMA	4 (8)		ont 7/8	
-	LI Front	12 youddin	ODI Junth	-	12	PULADADA	(80) E	T R Front	ont 7/8	Engine Hrs:
2	LU Middle			RO Middle				2 L MI	Middle	

Position	TD	Brand	PSI	Position	TD	Brand	PSI
LO Front	12	YOUGHANA	600	100 RO Front	12	HOLOHAMA	600
LI Front	12	HOUDHANT	100	100 RI Front	12	tor AHO301	100
LO Middle				RO Middle			
LI Middle				RI Middle			
LO Rear	12	YOUHAAAA	100	100 RO Rear	12	YOUOHAMA	100
LI Rear	12	HOUCHAND	all	100 RI Rear	12		100

ω

Position Depth L Front 7/9 R Front 7/9
Depth 7/g 7/g

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Mania Nent 4-18-25

Inspection Date: _

MARCIN NONINC

(Inspector signature)

Print Name:

1

Inspection conducted by:_

Company Name: Cox Automotive Mobility Fleet Services