

# ANNUAL VEHICLE INSPECTION REPORT

## VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER	DATE
610483931	W97011	08/01/24

MOTOR CARRIER OPERATOR <b>Egi Freight Inc dba Royal Line</b>	INSPECTOR'S NAME (PRINT OR TYPE) <b>JUGOSLAV KOVACEVIC</b>
ADDRESS <b>6850 W - 63rd St.</b>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <b>Chicago, IL 60638</b>	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER <b>1GK1P0622ND335050</b>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKE SYSTEM</b>				<b>e. Pitman Arm</b>
✓			a. Service Brakes	N/A			f. Power Steering
✓			b. Parking Brake System				g. Ball and Socket Joints
✓			c. Brake Drums or Rotors				h. Tie Rods and Drag Links
✓			d. Brake Hose	N/A			i. Nuts
✓			e. Brake Tubing				j. Steering System
✓			f. Low Pressure Warning Device				<b>8. SUSPENSION</b>
✓			g. Tractor Protection Valve	✓			a. Axle Positioning Parts
N/A			h. Air Compressor	✓			b. Spring Assembly
✓			i. Electric Brakes				c. Torque, Radius or Tracking Components
✓			j. Hydraulic Brakes				<b>9. FRAME</b>
✓			k. Vacuum Systems	✓			a. Frame Members
✓			l. Antilock Brake System	✓			b. Tire and Wheel Clearance
✓			m. Automatic Brake Adjusters	✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			<b>2. COUPLING DEVICES</b>				<b>10. TIRES</b>
✓			a. Fifth Wheels	N/A			a. Steer-Axle Tires
✓			b. Pintle Hooks	N/A			b. All Other Tires
✓			c. Drawbar/Towbar Eye	N/A			c. Speed-Restricted Tires
✓			d. Drawbar/Towbar Tongue				<b>11. WHEELS AND RIMS</b>
✓			e. Safety Devices	N/A			a. Lock or Side Ring
N/A			f. Saddle-Mounts	✓			b. Wheels and Rims
			<b>3. EXHAUST SYSTEM</b>	✓			c. Fasteners
			a. No leaks forward of/directly below the driver/sleeper compartment.	✓			d. Welds
N/A			b. Bus: No leaking/discharging in violation of standard.	N/A			<b>12. WINDSHIELD GLAZING</b>
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			<b>4. FUEL SYSTEM</b>	N/A			<b>13. WINDSHIELD WIPERS</b>
			a. No visible leak.				Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
N/A			b. Fuel Tank Filler Cap	N/A			<b>14. MOTORCOACH SEATS</b>
			c. Fuel tank securely attached.	N/A			Any passenger seat that is not securely fastened to the vehicle structure.
			<b>5. LIGHTING DEVICES</b>	✓			<b>15. REAR IMPACT GUARD</b>
✓			All lighting devices and reflectors required by Section 393 shall be operable.				In place, securely attached, proper size, proper placement (see 393.86).
			<b>6. SAFE LOADING</b>				<b>16. OTHER</b>
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				List any other condition(s) which may prevent safe operation of this vehicle.
✓			b. Front End Structure				
N/A			c. Intermodal Container Securement Devices				
			<b>7. STEERING MECHANISM</b>				
			a. Steering Wheel Free Play				
N/A			b. Steering Column				
			c. Front Axle Beam/All Other Steering Components				
			d. Steering Gear Box				

**PASS**

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.