

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

67129254

W99431

DATE

08/12/24

MOTOR CARRIER OPERATOR

Zigi Freight Inc dba Royal 3 Inc

ADDRESS

6850 W. 63rd St.

CITY, STATE, ZIP CODE

Chicago, IL 60638

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

Jugoslav KOUCEK

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

3H3V532K4N5602684

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System	✓			b. Front End Structure				13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors	✓			c. Intermodal Container Securement Devices	N/A			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose	N/A			7. STEERING MECHANISM				14. MOTORCOACH SEATS
✓			e. Brake Tubing				a. Steering Wheel Free Play	N/A			Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device				b. Steering Column				15. REAR IMPACT GUARD
✓			g. Tractor Protection Valve	N/A			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).
✓			h. Air Compressor	N/A			d. Steering Gear Box				16. OTHER
✓			i. Electric Brakes	N/A			e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes				f. Power Steering				
✓			k. Vacuum Systems				g. Ball and Socket Joints				
✓			l. Antilock Brake System				h. Tie Rods and Drag Links				
✓			m. Automatic Brake Adjusters				i. Nuts				
			2. COUPLING DEVICES				8. SUSPENSION				
N/A			a. Fifth Wheels	N/A			a. Axle Positioning Parts				
✓			b. Pintle Hooks				b. Spring Assembly				
✓			c. Drawbar/Towbar Eye				c. Torque, Radius or Tracking Components				
✓			d. Drawbar/Towbar Tongue				9. FRAME				
✓			e. Safety Devices	✓			a. Frame Members				
N/A			f. Saddle-Mounts	✓			b. Tire and Wheel Clearance				
			3. EXHAUST SYSTEM				10. TIRES				
N/A			a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓			a. Steer-Axle Tires				
N/A			b. Bus: No leaking/ discharging in violation of standard.	✓			b. All Other Tires				
N/A			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			c. Speed-Restricted Tires				
			4. FUEL SYSTEM				11. WHEELS AND RIMS				
N/A			a. No visible leak.	N/A			a. Lock or Side Ring				
N/A			b. Fuel Tank Filler Cap	✓			b. Wheels and Rims				
N/A			c. Fuel tank securely attached.	✓			c. Fasteners				
			5. LIGHTING DEVICES				d. Welds				
✓			All required lights/reflectors operable.	✓							

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.