

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
69060931	W94930
DATE 04/23/25	

MOTOR CARRIER OPERATOR ZIGI FREIGHT INC dba ROYAL3 INC	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOVACEVIC
ADDRESS 6850 W. 63rd STREET	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE CHICAGO, IL 60638	VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 1GR1P062XNJ324217
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED														
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM			
1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING						
☒	☐		a. Service Brakes	☒	☐		a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☐	☐	N/A	No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).			
☒	☐		b. Parking Brake System	☒	☐		b. Front End Structure	☐	☐	N/A	13. WINDSHIELD WIPERS			
☒	☐		c. Brake Drums or Rotors	☐	☐	N/A	c. Intermodal Container Securement Devices	☐	☐	N/A	No missing, Damaged, or inoperable wipers.			
☒	☐		d. Brake Hose	7. STEERING MECHANISM				14. MOTORCOACH SEATS						
☒	☐		e. Brake Tubbing	☐	☐	N/A	a. Steering Wheel Free Play	☐	☐	N/A	Seats securely fastened to the vehicle structure.			
☐	☐	N/A	f. Low Pressure Warning Device	☐	☐	N/A	b. Steering Column	15. REAR IMPACT GUARD						
☐	☐	N/A	g. Tractor Protection Valve	☐	☐	N/A	c. Front Axle Beam/All Other Steering Components	☒	☐		In place, securely attached, proper size, proper placement (see 393.86).			
☐	☐	N/A	h. Air Compressor	☐	☐	N/A	d. Steering Gear Box	16. OTHER						
☐	☐	N/A	i. Electric Brakes	☐	☐	N/A	e. Pitman Arm	List any other condition(s) which may prevent safe operation of this vehicle. 						
☐	☐	N/A	j. Hydraulic Brakes	☐	☐	N/A	f. Power Steering							
☐	☐	N/A	k. Vakum Systems	☐	☐	N/A	g. Ball and Socket Joints							
☒	☐		l. Antilock Brake System	☐	☐	N/A	h. Tie Rods and Drag Links							
☒	☐		m. Automatic Brake Adjusters	☐	☐	N/A	i. Nuts							
2. COUPLING DEVICES				☐	☐	N/A	j. Streering System							
☐	☐	N/A	a. Fifth Wheels	☐	☐	N/A	8. SUSPENSION							
☐	☐	N/A	b. Pintle Hooks	☐	☐	N/A	a. Axle Positioning Parts	List any other condition(s) which may prevent safe operation of this vehicle. 						
☐	☐	N/A	c. Drawbar/Towbar Eye	☐	☐	N/A	b. Spring Assembly							
☐	☐	N/A	d. Drawbar/Towbar Tongue	☐	☐	N/A	c. Torque, Radius or Tracking Components							
☐	☐	N/A	e. Safety Devices	☒	☐		9. FRAME							
☐	☐	N/A	f. Saddle-Mounts	☒	☐		a. Frame Members							
3. EXHAUST SYSTEM				☒	☐		b. Tire and Wheel Clearance	List any other condition(s) which may prevent safe operation of this vehicle. 						
☐	☐	N/A	a. No leaks forward of/ directly below the driver/ sleeper compartment.	☒	☐		c. Adjustable Axle Assemblies (Sliding Subframes)							
☐	☐	N/A	b. Bus: No leaking/ discharging in violation of standard.	☐	☐		10. TIRES							
☐	☐	N/A	c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☐	☐	N/A	a. Steer-Axle Tires							
☐	☐	N/A		☒	☐		b. All Other Tires							
4. FUEL SYSTEM				☐	☐	N/A	c. Speed-Restricted Tires	List any other condition(s) which may prevent safe operation of this vehicle. 						
☐	☐	N/A	a. No visible Leak.	11. WHEELS AND RIMS										
☐	☐	N/A	b. Fuel tank filler cap	☒	☐		a. Lock or Side Ring							
☐	☐	N/A	c. Fuel tank securely attached.	☒	☐		b. Wheels and Rims							
☒	☐			☒	☐		c. Fasteners							
5. LIGHTING DEVICES				☒	☐		d. Welds							
☒	☐		a. All required light/reflectors operable.	☒	☐									

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, ☒ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.