

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
610483918	W94931	06/27/24

MOTOR CARRIER OPERATOR Zig, Freight Inc dba Royal 3 Inc	INSPECTOR'S NAME (PRINT OR TYPE) Jugoslov Kovacevic
ADDRESS 6850 W. 63rd St	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Chicago, IL 60638	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 16R1P0621NJ324218
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				e. Pitman Arm
✓			a. Service Brakes	N/A			f. Power Steering
✓			b. Parking Brake System				g. Ball and Socket Joints
✓			c. Brake Drums or Rotors	N/A			h. Tie Rods and Drag Links
✓			d. Brake Hose				i. Nuts
✓			e. Brake Tubing				j. Steering System
			f. Low Pressure Warning Device				8. SUSPENSION
			g. Tractor Protection Valve	✓			a. Axle Positioning Parts
N/A			h. Air Compressor	✓			b. Spring Assembly
			i. Electric Brakes	✓			c. Torque, Radius or Tracking Components
			j. Hydraulic Brakes				9. FRAME
✓			k. Vacuum Systems	✓			a. Frame Members
✓			l. Antilock Brake System	✓			b. Tire and Wheel Clearance
			m. Automatic Brake Adjusters	✓			c. Adjustable Axle Assemblies (Sliding Subframes)
N/A			2. COUPLING DEVICES				10. TIRES
			a. Fifth Wheels	N/A			a. Steer-Axle Tires
✓			b. Pintle Hooks	N/A			b. All Other Tires
✓			c. Drawbar/Towbar Eye	N/A			c. Speed-Restricted Tires
✓			d. Drawbar/Towbar Tongue	N/A			11. WHEELS AND RIMS
✓			e. Safety Devices	✓			a. Lock or Side Ring
N/A			f. Saddle-Mounts	✓			b. Wheels and Rims
			3. EXHAUST SYSTEM				c. Fasteners
N/A			a. No leaks forward of/directly below the driver/sleeper compartment.	✓			d. Welds
N/A			b. Bus: No leaking/discharging in violation of standard.				12. WINDSHIELD GLAZING
N/A			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			4. FUEL SYSTEM				13. WINDSHIELD WIPERS
N/A			a. No visible leak.	N/A			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			b. Fuel Tank Filler Cap	N/A			14. MOTORCOACH SEATS
			c. Fuel tank securely attached.				Any passenger seat that is not securely fastened to the vehicle structure.
✓			5. LIGHTING DEVICES	✓			15. REAR IMPACT GUARD
			All lighting devices and reflectors required by Section 393 shall be operable.				In place, securely attached, proper size, proper placement (see 393.86).
✓			6. SAFE LOADING				16. OTHER
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				List any other condition(s) which may prevent safe operation of this vehicle.
N/A			b. Front End Structure				
			c. Intermodal Container Securement Devices				
			7. STEERING MECHANISM				
N/A			a. Steering Wheel Free Play				
			b. Steering Column				
			c. Front Axle Beam/All Other Steering Components				
			d. Steering Gear Box				

PASS

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, **NA** IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

