ANNUAL VEHICLE INSPECTION REPORT

					_ •	•												
						1	VEHICLE HISTORY RECORD											
								F	REPORT			FLEET UNIT NUMBER						
								DATE				1						
								INSPECTOR'S NAME (PRINT OR TYPE)										
ZIGI FREIGHT INC dba ROYAL3 INC								THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.										
6850 W. 63rd STREET							VES YES	✓ YES										
CITY, STATE, ZIP CODE CHICAGO, IL 60638							VEHICLE INDE	VEHICLE INDETIFICATION (🗸 AND COMPLETE) 🗌 LIC.PLATE NO. 🛛 VIN 🗌 OTHER										
VEHICLE TYPE TRACTOR TRAILER TRUCK BUS INSPECTION AGENCY/LOCATION (OPTIONAL)																		
VEHICLE COMPONENTS INSPECTED																		
ОК	NEEDS REPAIR	REPAIRED DATE	ITEM	ОК	NEEDS REPAIR	REPAIRED DATE	ITE	м	ОК	NEEDS REPAIR	REPAIRED DATE	ITEM						
			1. BRAKE SYSTEM				6. SAFE LOADI	IG				12. WINDSHEILD GLAZING						
			a. Service Brakes		_		 a. Vehicle parts, dunnage, spar 				N/A	No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).						
			b. Parking Brake System				secured.											
			c. Brake Drums or Rotors d. Brake Hose				h Eront End Stru	Front End Structure				13. WINDSHEILD WIPERS						
			e. Brake Tubbing					Intermodal Container										
			f. Low Pressure Warning			N/A	Securement D	evices			N/A	No missing, Damaged, or inoperable wipers.						
		N/A	Device				7. STEERING M	ECHANISM				14. MOTORCOACH SEATS						
		N/A	g. Tractor Protection Valve			N/A	a. Steering Whee	el Free Play				Seats securely fastened to the vehicle						
		N/A	h. Air Compressor			N/A	b. Steering Colur	nn			N/A	structure.						
		N/A	i. Electric Brakes			N/A	^{C.} Front Axle Bea					15. REAR IMPACT GUARD						
		N/A	j. Hydraulic Brakes				Other Steering	g Components				In place, securely attached, proper size,						
		N/A	k. Vakum Systems			N/A	d. Steering Gear	Box				proper placement (see 393.86).						
			I. Antilock Brake System			N/A	e. Pitman Arm											
			m. Automatic Brake Adjusters			N/A	f. Power Steerin					16. OTHER List any other condition(s)						
		NI / A	2. COUPLING DEVICES			N/A	g. Ball and Socke					which may prevent safe						
		N/A N/A	a. Fifth Wheels b. Pintle Hooks			N/A N/A	i. Nuts					operation of this vehicle.						
		N/A	c. Drawbar/Towbar Eye			N/A		Streering System										
		N/A	d. Drawbar/Towbar Tongue				8. SUSPENSION											
		N/A	e. Safety Devices				a. Axle Positionir	Axle Positioning Parts										
		, N/A	f. Saddle-Mounts				b. Spring Assemb	-										
			3. EXHAUST SYSTEM	-			c. Torque, Radiu	s or Tracking										
			a. No leaks forward of/				Components											
		N/A	directly below the driver/ sleeper compartment.				9. FRAME					DAČQEN //						
							a. Frame Membe					THOOLU//						
			 b. Bus: No leaking/ discharging in violation of 				b. Tire and Whee											
		N/A	standard.	_	_		 c. Adjustable Axl Assemblies (SI 	e iding Subframes)										
<u> </u>			c. Unlikely to burn, char,				1-	- /										
		N/A	or damage the electrical	10														
			wiring, fuel supply, or any combustible part of vehicle.			N/A	a. Steer-Axle Tire	25										
		4. FUEL SYSTEM				IN/A	b. All Other Tires											
		N/A	a. No visible Leak.			N/A	c. Speed-Restrict											
		N/A	b. Fuel tank filler cap				11. WHEELS AN											
		N/A	c. Fuel tank securely attached.				a. Lock or Side R											
		·	5. LIGHTING DEVICES				b. Wheels and Ri	ms										
-			a. All required light/reflectors				c. Fasteners											
			operable.				d. Welds											
	IN	ISTRUCTIO	ONS: MARK COLUMN ENTRIES TO VE	RIFY II	ISPECT		INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: \checkmark OK, \times NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE											

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.