

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

65650881

W94945

DATE

02/06/2024

MOTOR CARRIER OPERATOR

Zigi Freight LLC DBA Royal 3 Inc

ADDRESS

6850 W 63RD ST

CITY, STATE, ZIP CODE

CHICAGO IL 60638

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS
☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

JUGOSLAV KOUACEVIC

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

16R1PO 026 NJ 324232

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING			
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System	✓			b. Front End Structure	N/A			13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	N/A			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose								14. MOTORCOACH SEATS
✓			e. Brake Tubing	N/A							Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device								15. REAR IMPACT GUARD
N/A			g. Tractor Protection Valve								In place, securely attached, proper size, proper placement (see 393.86).
N/A			h. Air Compressor								16. OTHER
N/A			i. Electric Brakes								List any other condition(s) which may prevent safe operation of this vehicle.
N/A			j. Hydraulic Brakes								
✓			k. Vacuum Systems								
✓			l. Antilock Brake System								
✓			m. Automatic Brake Adjusters								
2. COUPLING DEVICES				7. STEERING MECHANISM							
N/A			a. Fifth Wheels				a. Steering Wheel Free Play				
✓			b. Pintle Hooks				b. Steering Column				
✓			c. Drawbar/Towbar Eye				c. Front Axle Beam/All Other Steering Components				
✓			d. Drawbar/Towbar Tongue				d. Steering Gear Box				
✓			e. Safety Devices				e. Pitman Arm				
N/A			f. Saddle-Mounts				f. Power Steering				
3. EXHAUST SYSTEM				8. SUSPENSION							
N/A			a. No leaks forward of/ directly below the driver/sleeper compartment.				a. Axle Positioning Parts				
N/A			b. Bus: No leaking/ discharging in violation of standard.				b. Spring Assembly				
N/A			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				c. Torque, Radius or Tracking Components				
4. FUEL SYSTEM				9. FRAME							
N/A			a. No visible leak.				a. Frame Members				
N/A			b. Fuel Tank Filler Cap				b. Tire and Wheel Clearance				
N/A			c. Fuel tank securely attached.				c. Adjustable Axle Assemblies (Sliding Subframes)				
5. LIGHTING DEVICES				10. TIRES							
✓			All required lights/reflectors operable.				a. Steer-Axle Tires				
							b. All Other Tires				
							c. Speed-Restricted Tires				
							11. WHEELS AND RIMS				
							a. Lock or Side Ring				
							b. Wheels and Rims				
							c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.