

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

65650970 W97040

DATE

02/28/2024

MOTOR CARRIER OPERATOR

Ziggy FREIGHT / NCDBA ROYAL 3100

ADDRESS

6850 W 63 RD ST

CITY, STATE, ZIP CODE

CHICAGO IL 60638

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

JUGOSLAV KOVAČEVIĆ

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

16RA P0626UD 335049

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒			1. BRAKE SYSTEM	☒			6. SAFE LOADING	☒			12. WINDSHIELD GLAZING
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			b. Parking Brake System	☒			b. Front End Structure	☒			13. WINDSHIELD WIPERS
☒			c. Brake Drums or Rotors	☒			c. Intermodal Container Securement Devices	☒			No missing, damaged, or inoperable wipers.
☒			d. Brake Hose	☒			7. STEERING MECHANISM	☒			14. MOTORCOACH SEATS
☒			e. Brake Tubing	☒			a. Steering Wheel Free Play	☒			Seats securely fastened to the vehicle structure.
☒			f. Low Pressure Warning Device	☒			b. Steering Column	☒			15. REAR IMPACT GUARD
☒			g. Tractor Protection Valve	☒			c. Front Axle Beam/All Other Steering Components	☒			In place, securely attached, proper size, proper placement (see 393.86).
☒			h. Air Compressor	☒			d. Steering Gear Box	☒			16. OTHER
☒			i. Electric Brakes	☒			e. Pitman Arm	☒			List any other condition(s) which may prevent safe operation of this vehicle.
☒			j. Hydraulic Brakes	☒			f. Power Steering	☒			
☒			k. Vacuum Systems	☒			g. Ball and Socket Joints	☒			
☒			l. Antilock Brake System	☒			h. Tie Rods and Drag Links	☒			
☒			m. Automatic Brake Adjusters	☒			i. Nuts	☒			
☒			2. COUPLING DEVICES	☒			j. Steering System	☒			
☒			a. Fifth Wheels	☒			8. SUSPENSION	☒			
☒			b. Pintle Hooks	☒			a. Axle Positioning Parts	☒			
☒			c. Drawbar/Towbar Eye	☒			b. Spring Assembly	☒			
☒			d. Drawbar/Towbar Tongue	☒			c. Torque, Radius or Tracking Components	☒			
☒			e. Safety Devices	☒			9. FRAME	☒			
☒			f. Saddle-Mounts	☒			a. Frame Members	☒			
☒			3. EXHAUST SYSTEM	☒			b. Tire and Wheel Clearance	☒			
☒			a. No leaks forward of/ directly below the driver/sleeper compartment.	☒			c. Adjustable Axle Assemblies (Sliding Subframes)	☒			
☒			b. Bus: No leaking/ discharging in violation of standard.	☒			10. TIRES	☒			
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒			a. Steer-Axle Tires	☒			
☒			4. FUEL SYSTEM	☒			b. All Other Tires	☒			
☒			a. No visible leak.	☒			c. Speed-Restricted Tires	☒			
☒			b. Fuel Tank Filler Cap	☒			11. WHEELS AND RIMS	☒			
☒			c. Fuel tank securely attached.	☒			a. Lock or Side Ring	☒			
☒			5. LIGHTING DEVICES	☒			b. Wheels and Rims	☒			
☒			All required lights/reflectors operable.	☒			c. Fasteners	☒			
☒				☒			d. Welds	☒			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.