

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER	DATE
66681530	251824	05/20/24

MOTOR CARRIER OPERATOR

Zigi Freight Inc John Royal 3 Inc

ADDRESS 6850 W. 63rd St.

CITY, STATE, ZIP CODE Chicago, IL 60638

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS
☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

JUGOSLAV KORACEVIC

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE)

☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 1J3V532D2P1387A4

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			1. BRAKE SYSTEM				e. Pitman Arm
✓			a. Service Brakes				f. Power Steering
✓			b. Parking Brake System				g. Ball and Socket Joints
✓			c. Brake Drums or Rotors				h. Tie Rods and Drag Links
✓			d. Brake Hose				i. Nuts
✓			e. Brake Tubing				j. Steering System
			f. Low Pressure Warning Device				8. SUSPENSION
			g. Tractor Protection Valve				a. Axle Positioning Parts
			h. Air Compressor	✓			b. Spring Assembly
N/A			i. Electric Brakes	✓			c. Torque, Radius or Tracking Components
			j. Hydraulic Brakes				9. FRAME
✓			k. Vacuum Systems	✓			a. Frame Members
✓			l. Antilock Brake System	✓			b. Tire and Wheel Clearance
			m. Automatic Brake Adjusters	✓			c. Adjustable Axle Assemblies (Sliding Subframes)
N/A			2. COUPLING DEVICES				10. TIRES
✓			a. Fifth Wheels				a. Steer-Axle Tires
✓			b. Pintle Hooks	N/A			b. All Other Tires
✓			c. Drawbar/Towbar Eye	✓			c. Speed-Restricted Tires
✓			d. Drawbar/Towbar Tongue	N/A			11. WHEELS AND RIMS
N/A			e. Safety Devices				a. Lock or Side Ring
			f. Saddle-Mounts	N/A			b. Wheels and Rims
			3. EXHAUST SYSTEM	✓			c. Fasteners
			a. No leaks forward of/directly below the driver/sleeper compartment.	✓			d. Welds
N/A			b. Bus: No leaking/discharging in violation of standard.				12. WINDSHIELD GLAZING
N/A			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			4. FUEL SYSTEM				13. WINDSHIELD WIPERS
			a. No visible leak.	N/A			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
N/A			b. Fuel Tank Filler Cap				14. MOTORCOACH SEATS
			c. Fuel tank securely attached.	N/A			Any passenger seat that is not securely fastened to the vehicle structure.
✓			5. LIGHTING DEVICES	✓			15. REAR IMPACT GUARD
			All lighting devices and reflectors required by Section 393 shall be operable.				In place, securely attached, proper size, proper placement (see 393.86).
			6. SAFE LOADING				16. OTHER
N/A			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				List any other condition(s) which may prevent safe operation of this vehicle.
N/A			b. Front End Structure				
			c. Intermodal Container Securement Devices				
			7. STEERING MECHANISM				
N/A			a. Steering Wheel Free Play				
			b. Steering Column				
			c. Front Axle Beam/All Other Steering Components				
			d. Steering Gear Box				

PASS

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.