

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
64429976	251824
DATE 06/27/23	

MOTOR CARRIER OPERATOR Zigi Freight Inc dba Royal 3inc	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOVACEVIC
ADDRESS 6850 W. 63rd St	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE Chicago, IL 60638	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER 1JTV532D2PL387174
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED							
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			1. BRAKE SYSTEM				12. WINDSHIELD GLAZING
✓			a. Service Brakes				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System	N/A			13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose	N/A			14. MOTORCOACH SEATS
✓			e. Brake Tubing				Seats securely fastened to the vehicle structure.
			f. Low Pressure Warning Device				15. REAR IMPACT GUARD
			g. Tractor Protection Valve				In place, securely attached, proper size, proper placement (see 393.86).
N/A			h. Air Compressor	N/A			16. OTHER
			i. Electric Brakes				List any other condition(s) which may prevent safe operation of this vehicle.
			j. Hydraulic Brakes				
			k. Vacuum Systems				
✓			l. Antilock Brake System	N/A			
✓			m. Automatic Brake Adjusters				
			2. COUPLING DEVICES				
N/A			a. Fifth Wheels	N/A			
✓			b. Pintle Hooks				
✓			c. Drawbar/Towbar Eye				
✓			d. Drawbar/Towbar Tongue				
✓			e. Safety Devices				
N/A			f. Saddle-Mounts				
			3. EXHAUST SYSTEM				
			a. No leaks forward of/ directly below the driver/ sleeper compartment.				
N/A			b. Bus: No leaking/ discharging in violation of standard.				
N/A			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				
			4. FUEL SYSTEM				
			a. No visible leak.				
N/A			b. Fuel Tank Filler Cap				
			c. Fuel tank securely attached.				
✓			5. LIGHTING DEVICES				
			All required lights/reflectors operable.				
			6. SAFE LOADING				
			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				
			b. Front End Structure				
			c. Intermodal Container Securement Devices				
			7. STEERING MECHANISM				
			a. Steering Wheel Free Play				
			b. Steering Column				
			c. Front Axle Beam/All Other Steering Components				
			d. Steering Gear Box				
			e. Pitman Arm				
			f. Power Steering				
			g. Ball and Socket Joints				
			h. Tie Rods and Drag Links				
			i. Nuts				
			j. Steering System				
			8. SUSPENSION				
			a. Axle Positioning Parts				
			b. Spring Assembly				
			c. Torque, Radius or Tracking Components				
			9. FRAME				
			a. Frame Members				
			b. Tire and Wheel Clearance				
			c. Adjustable Axle Assemblies (Sliding Subframes)				
			10. TIRES				
			a. Steer-Axle Tires				
			b. All Other Tires				
			c. Speed-Restricted Tires				
			11. WHEELS AND RIMS				
			a. Lock or Side Ring				
			b. Wheels and Rims				
			c. Fasteners				
			d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.