

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

67129248

251825

DATE

08/28/24

MOTOR CARRIER OPERATOR

Zigi Freight Inc dba Royal 3 Inc

INSPECTOR'S NAME (PRINT OR TYPE)

Jugoslav Kovacevic

ADDRESS

6850 W. 63rd St

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

YES

CITY, STATE, ZIP CODE

Chicago, IL 60638

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

1JJV532J4PL387175

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			a. Service Brakes	N/A			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System	✓			b. Front End Structure				
✓			c. Brake Drums or Rotors	N/A			c. Intermodal Container Securement Devices	N/A			13. WINDSHIELD WIPERS
			d. Brake Hose								No missing, damaged, or inoperable wipers.
			e. Brake Tubing								
			f. Low Pressure Warning Device								14. MOTORCOACH SEATS
			g. Tractor Protection Valve								Seats securely fastened to the vehicle structure.
			h. Air Compressor	N/A			a. Steering Wheel Free Play	N/A			
			i. Electric Brakes				b. Steering Column				15. REAR IMPACT GUARD
			j. Hydraulic Brakes				c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).
			k. Vacuum Systems				d. Steering Gear Box				
✓			l. Antilock Brake System	N/A			e. Pitman Arm				16. OTHER
			m. Automatic Brake Adjusters				f. Power Steering				List any other condition(s) which may prevent safe operation of this vehicle.
			2. COUPLING DEVICES				7. STEERING MECHANISM				
N/A			a. Fifth Wheels				a. Steering Wheel Free Play				
✓			b. Pintle Hooks	N/A			b. Steering Column				
✓			c. Drawbar/Towbar Eye				c. Front Axle Beam/All Other Steering Components				
✓			d. Drawbar/Towbar Tongue				d. Steering Gear Box				
N/A			e. Safety Devices				e. Pitman Arm				
			f. Saddle-Mounts				f. Power Steering				
			3. EXHAUST SYSTEM				8. SUSPENSION				
			a. No leaks forward of/ directly below the driver/sleeper compartment.	✓			a. Axle Positioning Parts				
			b. Bus: No leaking/ discharging in violation of standard.	✓			b. Spring Assembly				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			c. Torque, Radius or Tracking Components				
			4. FUEL SYSTEM				9. FRAME				
			a. No visible leak.	✓			a. Frame Members				
			b. Fuel Tank Filler Cap	✓			b. Tire and Wheel Clearance				
			c. Fuel tank securely attached.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
			5. LIGHTING DEVICES				10. TIRES				
✓			All required lights/reflectors operable.	✓			a. Steer-Axle Tires				
				✓			b. All Other Tires				
				✓			c. Speed-Restricted Tires				
				✓							
				✓			11. WHEELS AND RIMS				
				✓			a. Lock or Side Ring				
				✓			b. Wheels and Rims				
				✓			c. Fasteners				
				✓			d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, ☒ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.