

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
64871410	289470
DATE 11/03/23	

MOTOR CARRIER OPERATOR Zigi Freight Inc dba Royal 3 Inc	INSPECTOR'S NAME (PRINT OR TYPE) Jugoslav Kovacevic
ADDRESS 6850 W. 63rd St.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE Chicago, IL 60638	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER 1GRAP062XJT106132
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM											
✓			a. Service Brakes				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			b. Parking Brake System	N/A			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			c. Brake Drums or Rotors	-			b. Front End Structure				13. WINDSHIELD WIPERS
✓			d. Brake Hose	N/A			c. Intermodal Container Securement Devices	N/A			No missing, damaged, or inoperable wipers.
			e. Brake Tubing				7. STEERING MECHANISM				14. MOTORCOACH SEATS
			f. Low Pressure Warning Device				a. Steering Wheel Free Play	N/A			Seats securely fastened to the vehicle structure.
			g. Tractor Protection Valve				b. Steering Column				15. REAR IMPACT GUARD
			h. Air Compressor	N/A			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).
			i. Electric Brakes				d. Steering Gear Box				16. OTHER
			j. Hydraulic Brakes				e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
			k. Vacuum Systems				f. Power Steering				
			l. Antilock Brake System	N/A			g. Ball and Socket Joints				
			m. Automatic Brake Adjusters				h. Tie Rods and Drag Links				
2. COUPLING DEVICES											
			a. Fifth Wheels				i. Nuts				
			b. Pintle Hooks	N/A			j. Steering System				
			c. Drawbar/Towbar Eye				8. SUSPENSION				
			d. Drawbar/Towbar Tongue				a. Axle Positioning Parts				
			e. Safety Devices				b. Spring Assembly				
			f. Saddle-Mounts				c. Torque, Radius or Tracking Components				
3. EXHAUST SYSTEM											
			a. No leaks forward of/ directly below the driver/ sleeper compartment.				9. FRAME				
			b. Bus: No leaking/ discharging in violation of standard.				a. Frame Members				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				b. Tire and Wheel Clearance				
4. FUEL SYSTEM											
			a. No visible leak.				c. Adjustable Axle Assemblies (Sliding Subframes)				
			b. Fuel Tank Filler Cap				10. TIRES				
			c. Fuel tank securely attached.				a. Steer-Axle Tires				
5. LIGHTING DEVICES											
			All required lights/reflectors operable.				b. All Other Tires				
							c. Speed-Restricted Tires				
11. WHEELS AND RIMS											
							a. Lock or Side Ring				
							b. Wheels and Rims				
							c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 393